



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee		Licensee Representative	
Elizabeth C. Turner		No personnel on site	
Licence No. / Expiry		Representative's Title	
3BC-MBP1114			
Land / Other Authorizations			
Date of Inspection		Inspector	
June 27, 2017		Jonathan Mesher	
Activities Inspected			
<input type="checkbox"/> Municipality	<input type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Roads/Hauling	<input checked="" type="checkbox"/> Other: Camp	<input type="checkbox"/> Other:	<input type="checkbox"/> Reclamation
<input type="checkbox"/> Fuel Storage			

Conditions:		A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected	
Water Use		Condition	Comment	Site Conditions		Condition	Comment
Intake/Screen	NI			Water Management Structures		NI	
Flow Measure. Device	NI			Culverts / Bridges		NI	
Source:	A			Drainage		NI	
Water Use:	A			Erosion / Sediment		NI	
Recirculation (y /n)	NI			Mitigation Measures		NI	
				Reclamation Activities		A	
				Materials Storage		NI	
Waste Disposal				Signage		A	
Waste Water	A						
Solid Waste	A			Monitoring			
Hazardous Waste	A			Sample Collection / Analysis		A	
*The number in the comments field will correspond with specific comments provided below.							
Samples taken by Inspector:			Location(s):				
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No							

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Background			
Nunavut Water Licence 3BC-MBP1010, issued to Elizabeth C. Turner, allowed for the use of 5 cubic metres per day and the deposit of waste between the dates of July 16, 2010 and December 31, 2010. The authorization was issued to support research at the Mesoproterozoic Basins Project located on Devon Island and Ellesmere Island within the Qikiqtani Region, Nunavut.			
Inspectors Statement			
On June 27, 2017 an inspection of the water Licence was conducted on this project to ensure all uses of water and deposits of waste had ceased.			
No uses of water or deposits of waste in contravention of section 11 and 12 of the Nunavut Waters and Nunavut Surface Rights Tribunal Act were noted.			
Based on the evidence made available to INAC and the site inspection, no concerns were noted with the site and no further inspection of this site related to this project will be conducted.			

Inspector's Name	
Jonathan Mesher	
Signature	
Signature on original	
Date	
September 25, 2017	