

NWB Annual Report

Year being reported: 2010



License No: 3BC-NWT0810

Issued Date: July, 2008

Expiry Date: September 30, 2010

Project Name: Northern Watch Technology Demonstration Project

Licensee: Defence Research and Development Canada - Atlantic

Mailing Address: P.O. Box 1012  
Dartmouth, NS  
B2Y 3Z7

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Defence Construction Canada  
Tamara Van Dyck - Environmental Project Coordinator

General Background Information on the Project (\*optional):

Northern Watch is a federal Department of National Defence Maritime Surveillance capability demonstration project conducted by Defence Research and Development Canada. The project will run from through to 2015

Licence Requirements: the licensee must provide the following information in accordance with

Select



Select

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s): melt water stream

Water Quantity:

5/day

Quantity Allowable Domestic (cu.m)

0.628/day

Actual Quantity Used Domestic (cu.m)

0

Quantity Allowable Drilling (cu.m)

0

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☒ Solid Waste Disposal☒ Sewage☐ Drill Waste☒ Greywater☐ Hazardous☐ Other:

Additional Details:

Solid waste sent to Resolute Bay for Disposal. Liquid waste and grey water flow into extensive gravel bed that the camp is built upon.

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

### Revisions to the Abandonment and Restoration Plan

N/A - not applicable ▼

Additional Details:

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details described below ▼

Additional Details:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details described below ▼

Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

**Date Submitted:**

April 28, 2011

**Submitted/Prepared by:**

Tamara Van Dyck (DCC) on behalf of DRDC

**Contact Information:**

**Tel:** (613) 995-9741

**Fax:** (613) 996-9847

**email:** [Tamara.VanDyck@dcc-cdc.gc.ca](mailto:Tamara.VanDyck@dcc-cdc.gc.ca)

## GPS Coordinates for water sources utilized

[illegible]

## GPS Locations of areas of waste disposal

[illegible]