

## WATER LICENCE INSPECTION FORM

☑ Original☑ Follow-Up Report

Licensee			Licensee Re	presentativ	re				
Dr. Helen R. Smyth  None Present									
CASP, University of C	Cambridge								
West Building									
181a Huntingdon Road									
Cambridge, CB3 0DH, UK									
Email: helen.smyth@casp.cam.ac.uk									
Licence No. / Expiry			Representa	tive's Title					
3BC-PRO0914 N/A									
Land / Other Authorizations Land / Other Authorizations									
Date of Inspection			Inspector						
04/07/2014			A.Kein	1					
Activities Inspected			71.110111	•					
	] Drilling	☐ Mining	☐ Cor	struction		Reclamation	□F	uel Storage	<u>.</u>
☐ Roads/Hauling ☐	Other: Water Discha	rge	⊠ Oth	ner:					
Conditions: A - Ac	ceptable	C - Concern	U - Unaccept	table	NIA	Not Applicable	NII	- Not Insp	acted
	•		<u>-</u>			• •			
Water Use	Condition Comment	Site Condition		Condition	Comment	Haz/Mat Manage	ment	Condition	Comment
Intake/Screen	NI	Water Manager	ment Structures	NA		Storage		NA	
Flow Measure. Device	NI	Culverts / Brid	ges	NA		Spills		NA	
Source:		Drainage		NA		Spill Plan		NA	
Water Use:	NI	Erosion / Sedir	ment	NA					
Recirculation ( y /n)	N	Mitigation Me		NA		Administrative			
Recirculation ( y 711)	IV	Reclamation A		NA				NI	
						Records			
		Materials Stor	age	NA		Reports		Α	
Waste Disposal		Signage		NA		Plans		Α	
Waste Water	NA					Notifications			
Solid Waste	NA	Monitoring		<u> </u>		Other			
Hazardous Waste	NA	Sample Collect	tion / Analysis	NA					
*TI	ho number in the c	eammonts field w	vill correspond	with specif	fic com	l ments provided belov	147		
			viii corresporia v	vitii specii	IIC COIIII	nerits provided belov	VV.		
Samples taken by Inspec	ctor:	Location(s):							
☐ Yes ☐ No									
SECTION 1	Comments (s)	Non	-Compliance w	ith Act or	Licence	e(s) Act	ion Re	auired (s	)
SECTION 1 Comments (s) Non-Compliance with Act or Licence (s) Action Required (s)  On July 4 <sup>th</sup> the Inspector attended the locations of sites listed in the annual report (Field Report) from 2013 to inspect the short									
term/ low impact camp									
that no evidence of occu									
								c urcu. T	TIC
sites were both found in what appeared to be their natural state with no evidence of disturbance.									
During a review of the administrative responsibilities associated with the current license it was identified by the Inspector that an									
Approval for the Use of Waters or the Deposit of Waste Without a License using the same (PRO) license identifiers for the same									
project has been issued under a different same for what appears to be the same activity in the same general location as the above									
issued Water License.									
8WLC-PRO1415									
Dr. Peter Hülse									
CASP, University of Cambridge West Building									
West Building 181a Huntington Road									
Cambridge, CB3 0DH									
Email: peter.hulse@casp.cam.ac.uk									
The current Inspection Report has been compiled based on sites listed as visited in 2013, there was not an inspection conducted related to the Authorization without a License locations.									
The Inspector seeks clarification from the Licensee and from the Nunavut Water Board on which authority is in effect and whether or not the Licensee intends to continue to operate under the authority of the issued License or Authorization without a license.									
SECTION 2	Comments (s)	Non	-Compliance w	ith Act or	Licence	e (s) Act	ion Re	<b>quired</b> (s	)
Click here to enter to			•						
			Commission	41a A a 4	Liser		ion D	autino al /	``
SECTION 3	Comments (s)	Non	-Compliance w	ith Act or	Licence	:, (S) Act	ion ke	<b>quired</b> (s	)
Click here to enter text.									





Licensee or Representative	Inspector's Name		
	A.Keim		
Signature	Signature		
	-Sent by Email – original on file		
Date	Date		
	July 4, 2014		

Office Use Only:	Follow-up report to be issued by Inspector	☐ Yes   No

