



Field Operations Division  
PO Box 2200  
Iqaluit, NU X0A 0H0

10 September 2014

Martin McCurdy  
Geological Survey of Canada  
Natural Resources Canada  
601 Booth St.  
Ottawa, ON K1A 0E8  
Email: [mmccurdy@NRCan-RNCan.gc.ca](mailto:mmccurdy@NRCan-RNCan.gc.ca)

RE: Water Licence 3BC-SSS1212

An inspection was conducted on July 12, 2014 of two sites in relation to this water licence. The camp, located at N65 22 07.0 W105 11 32.0, and a fuel cache, located at N66 04 23.0 W105 14 17.0 were visited, coordinates for which were provided at the request of the Inspector.

No evidence of use was found at either location.

No annual report has been filed in relation to this project.

When the Board feels that the administrative requirements have been met, no further inspection will be required prior to cancellation of this licence.

Regards,

Eva Paul  
Water Resources Officer  
PO Box 2200  
Iqaluit, NU X0A 0H0  
Phone: 867-975-4548  
Mobile: 867-222-6590  
Fax: 867-979-6445  
E-mail: [Eva.Paul@aadnc-aadnc.gc.ca](mailto:Eva.Paul@aadnc-aadnc.gc.ca)

CC: Phyllis Beaulieu, Manager of Licensing, NWB  
Erik Allain, Manager of Field Operations, AANDC