Phyllis Beaulieu

From: Andrew Keim [keima@inac-ainc.gc.ca]
Sent: Friday, October 12, 2007 11:05 AM

To: Phyllis Beaulieu

Subject: Fwd:

Attachments: DSC01489.JPG; Main Camp Original Contours.pdf





DSC01489.JPG Main Camp (74 KB) ginal Contours.pc

as per your request... sorry

>>> "Kenny Theriault" <KennyT@nunalogistics.com> 10/09/07 9:24 PM >>> Mr. Keim

Here is the picture and Pre-Leveling Topographic Survey we discussed on the phone last week CIDM # 170840 Baker Lake main camp. I explained to you at the time of the inspection, the sections which are pointed out on the report

are now taking care of. Noted Part- G- TEG transfer tank within the

compound without a spill kit, I am attaching the picture with the Pre- Leveling Topographic Survey, As for Part B General Conditions I have been in contact with Glen Murphy of Nampcy Solutions Ltd. Who is our surveyor here on location and has said this is what you would want to look at Pre-leveling Topographic Survey for our main camp.

Would it be possible to reply back to me stating this is what you needed and we may move on with the next process of the Water License?

Part B: General Conditions: Pre-Leveling Topographic Survey

Part D Applying to the Waste Disposal the removal of toilet waste is disposed in cooperation with the Municipal of Baker Lake, which is empted at the Hamlet Lagoon and is based on our estimate volume of 7300 liters per day. (Taken care of)

Part G Applying to Spill Contingency Planning It was noted at the time of

inspection 5 gallon pails of gear oils along with other drums containing petroleum products, were being stored with out a secondary containment.

Sense the time of the report all petroleum products have been moved to the forward mechanical shop on the AWR.



