WATER USE INSPECTION REPORT

Date: August 4, 2009	Licensee Rep. (Name/Title): Ed Murphy A/Hamlet Foreman		
Licensee: Hamlet of Arviat		Licence No.:	NWB3ARV0308- Expired

WATER SUPPLY

Source(s): Wolf River Creek	Quantity used: Unknown –
Owner:/Operator: Government of Nunavut	Treatment systems operated by C&GS, Gov. Nu.

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Intake Facilities: A	Storage Structure: A	Treatment Systems: A	Chemical Storage: NI
Flow Meas. Device: U	Conveyance Lines: A	Pumping Stations: A	Screen : NI

Comments: The Government of Nunavut, Dept. of Community and Government Services provides the oversight and drinking water treatment services for the community. Staff members from the Government of Nunavut were not available to provide access to the pumping station for inspection.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): Primary cell and wetlands treatment

Natural Water Body: No	Continuous Discharge (land or wate	r): seepages
Seasonal Discharge: Decanting	Wetlands Treatment: Y	Trench: None

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality: ∪	Decant Structure: NI	Erosion: A
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: U
Dams, Dykes: NI	Freeboard: A	Spills: A
Construction: NI	O&M Plan: U	A&R Plan: U
Periods of Discharge: Cont.	Effluent Discharge Rate: Unknown	

Comments: Sewage from Lagoon seeps continually through the toe of the berm and then overland to the ocean. Samples were collected. Decanting of the lagoon was undertaken earlier in the season. No notification was provided the inspector.

Solid Waste: Non-combustible waste consolidated at waste metals area.

Owner/Operator: Hamlet of Arviat

Landfill: A- evidence of segregation	Burn & Landfill: A	Other:
--------------------------------------	--------------------	--------

Comments: Water management from the municipal waste management area is required to address runoff and ponding of contact water outside the management area.

FUEL STORAGE:

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: NI	Water within Berms: NI	Evidence of Leaks: NI
Drainage Pipes: NI	Pump Station & Catchments Berm: NI	
Pipeline Condition: NI	Condition of Tanks: NI	

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collec	Samples Collected: 0 Owner /Operator: No sa		o samples from Municipality have been submitted
Samples Collected: 3 INAC: Potable (Reservoir), Effluent discharge, Dump Leachate		rvoir), Effluent discharge, Dump Leachate	
Signs Posted	SNP: None		Warning: Some signs were noted
Records & Reporting: No records of water usage, waste discharge, Operations manuals, or required Plans.			
Geotechnical Inspection: N/A			

Non-Compliance of Act or Licence: The Hamlet of Arviat's water license expired in December 2008. The Community has not been collecting samples nor filing the required paperwork. The Municipality continues to operate in contravention of the Nunavut water and Nunavut Surface Rights Tribunal Act. It is noted that on January 5th, 2009 a type A license application was submitted. The application was incomplete and to date no further submissions have been received.

Inspector's Name	Inspector's Signature
A.Keim	Sent by E-mail