

NUNAVUT SPILL REPORT (Oil, Gas, Hazardous Chemicals or other Materials)

24-Hour Report Line 24-Hour Report Line 24-Hour Report Line

Phone 647-61 (867) 920-8130
Fax 647-61 (867) 873-6824

A. Report Date and Time December 20, 2001 1130 hours		B. Date and Time of Spill (if known) December 20, 2001		C. Original Report ☒ Original Report ☐ Update No. _____		Spill Number 02-26	
D. Location and Map Coordinates (if known) and Direction (if known) House #221, Clyde River, Nunavut 70° 29'N 68° 31' West						RECEIVED JAN 24 2002	
E. Party Responsible for Spill (Full Name and Address) Clyde River Housing Association							
F. Product(s) Spilled and Estimated Quantities (provide metric volumes/weights if possible) Approximately 15 gallons of diesel fuel							
G. Cause of Spill Cracked Fuel Line							
H. Is Spill Terminated? ☒ Yes ☐ No		I. If Spill is Continuing, give Estimated Time No		J. Is Further Spillage Possible? ☐ Yes ☒ No		K. Extent of Contamination (in square meters if possible) 1-2 square meters	
L. Factors Affecting Spill or Recovery (weather conditions, terrain, snow cover, etc.) Spill is located directly underneath building. Also ground is frozen solid so soil collection is impossible.						M. Containment (natural depression, dikes, etc.) None	
N. Action, if any, taken or Proposed to Contain, Remove, Clean up or Dispose of Product(s) and Contaminated Materials None							
O. Do You Require Assistance? ☒ No ☐ Yes				P. Possible Hazards to Persons, Property or Environment (e.g. fire, drinking water, fish or wildlife) None			
Q. Comments and/or Recommendations This site will be revisited in the spring to see if contaminated soil needs to be removed. It is difficult to assess the amount of fuel spilled at this site because the crack in the pipe was very small, and therefore it may have been leaking for some time without being noticed. However, from examination of the site, I do not believe more than 15 gallons of fuel was spilled due to the size of the contaminated area.						FOR SPILL LINE USE ONLY Lead Agency GAD Spill Significance Lead Agency Contact and Time GAD Is this file now closed? Yes	
Reported By Jason Haimu		Position, Employer, Location Housing Worker, Clyde River, Nunavut		Telephone (867) 924-6273		Reported To Devin CONROY	
		Position, Employer, Location Wildlife Officer, Department of Sustainable Development, Clyde River, NU		Telephone (867) 924-6235			