

WATER USE INSPECTION REPORT

Date: July 23,2009	Licensee Rep. (Name/Title): Jerry Paniyuk- Mayor
Licensee: Municipality of Coral Harbour	Licence No.: 3BM-COR0813

WATER SUPPLY

Source(s): Post River to Reservoir		Quantity used: No records for review	
Owner:/Operator: Municipality of Coral Harbour			
Indicate: <b>A</b> - Acceptable <b>U</b> - Unacceptable <b>NA</b> - Not Applicable <b>NI</b> - Not Inspected			
Intake Facilities: A	Storage Structure: A	Treatment Systems: A	Chemical Storage: A
Flow Meas. Device: A	Conveyance Lines: A	Pumping Stations: A	Screen : NA

**Comments:** Water is collected into a reservoir lake from the river and then taken in via pumping station where it is treated and distributed by truck in the community. An Inspection was not completed last year. It is expected that water will be drawn from the river in Sept 2009.

WASTE DISPOSAL

**Sewage:** Sewage Treatment System (Prim./Sec/Ter.): Primary

Natural Water Body: No	Continuous Discharge (land or water): None	
Seasonal Discharge: Fall	Wetlands Treatment: None	Trench: None

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality: A	Decant Structure: NI	Erosion: None
Discharge Meas. Device: NA	Dyke Inspection: NI	Seepages: None
Dams, Dykes: A	Freeboard: A	Spills: None
Construction: NI	O&M Plan: NI	A&R Plan: NI
Discharge: None	Effluent Discharge Rate: Unknown	

**Comments:** Lagoon was noted in good condition, fencing and signage throughout area. Low lying tundra beyond lagoon may be providing polishing to decant.

**Solid Waste:** No Haz- mat storage, land fill, bulk metal wastes in same general area

**Owner/Operator:** Municipality of Pond Inlet

Landfill: NA	Burn & Landfill: A	Other: Haz mat area required as well as some remedial works
--------------	--------------------	---

**Comments:** Coral harbour requires a Haz mat storage area with appropriate liner and proper segregation of wastes must be undertaken. No leaching off site was identified at time of inspection. The Bulk Metals area requires sorting.

FUEL STORAGE:

**Waste Oil Storage:** NI – None noted **Owner/Operator:** Government of Nunavut

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: NI	Water within Berms: NI	Evidence of Leaks: NI
Drainage Pipes: Ni	Pump Station & Catchments Berm: NI	
Pipeline Condition: NI	Condition of Tanks: Unknown	

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected		Owner /Operator: None	
2		INAC: Runoff downstream of lagoon and potable.	
Signs Posted	SNP: Present		Warning: Signage present
Records & Reporting: records to be provided in annual report			
Geotechnical Inspection: N/A			

**Non-Compliance of Act or Licence:** The Municipality is working on achieving compliance with the issued License. The Municipality wants to undertake road construction works that will involve the installation of a culvert over a non-fish bearing melt water stream. Mayor was advised to contact the board about a submission of an amendment application under the current license.

A.Keim

Inspector’s Name

Sent by E-mail

Inspector’s Signature