



N.W.T. SPILL REPORT

(Oil, Gas, Hazardous Chemicals or other Materials)

24-Hour Report Line

Phone 867-920-8130
Fax 867-920-8130

24-Hour Report Line

A Report date and time 30/05/00 1:30 PM		B Date and time of spill (if known) 30/05/00 11 AM		C ☐ Original report ☐ Update no. _____		Spill number INTERNAL	
D Location and map coordinates (if known) and direction (if moving) Hamlet Mechanic Garage yard							
E Party responsible for spill Fuel Delivery Contractor - Trim							
F Product(s) spilled and estimated quantities (provide metric volumes/weights if possible) P50 Motive Approx 90 liters						MAY 30 2000	
G Cause of spill Valve on the Delivery Truck Tank broke off							
H Is spill terminated? ☒ yes/ ☐ no/		I If spill is continuing, give estimated rate 10 L/min		J Is further spillage possible? ☐ yes/ ☒ no/		K Extent of contaminated area (in square metres if possible) Approx 12 sq. metres	
L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) None				M Containment (natural depression, dykes, etc.) None			
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials Scoop ground with loader bucket & shovel contents in 45 gal. drums to be stored at Hazardous Waste site pending proper disposal							
O Do you require assistance? ☒ yes, describe: ☐ no				P Possible hazards to persons, property, or environment; eg: fire, drinking water, fish or wildlife None			
Q Comments and/or recommendations Notified Nunavut Water Board. Notified RWD Officer, who offered assistance on how the spill could best be cleaned up.							
Reported by J. N. Dufjel		Position, Employer, Location Hamlet of Iqaluit, Housing + Works				Telephone 867-360-6927	
Reported to P. J. Dufjel		Position, Employer, Location Hamlet of Iqaluit, Housing + Works				Telephone 867-360-6927	