金色型像的复数形式 1917年19日,1918年19日,1918年19日,1918年19日,1918年19日,1918年19日,1918年19日,1918年19日,1918年19日,1918年19日,1918年19日,1



Community Lands Administrator Municipal Liaison Officer Municipality of Hall Beach Bag #3, Hall Beach, Nunavut XOA OKO Ph: 867-928-8961 Fax: 867-928-8962

Adule Chris Senior Baffin Community Planner CGS, Cape Dorset, NU

RE: Water Ponds in proposed Survey Areas

Dear Sir.

As per your request, please find information regarding the water bodies (ponds) located on the areas that have been identified for surveying later this summer.

- > 610-001a
 - o Water body I is a snow dumpsite during the winter that melts away in spring and dries up during the summer.
 - o Water bodies 2, 3, & 4 no longer exists has there is an access road;
 - Water body 5 is a muddy area that dries up during the summer.
- ≻ 610-001Ъ
 - Water body 1 is used as a snow dumpsite in winter before melting away in spring and dries up during the summer,
- ≥ 610-001c
 - o Water body 1 is a muddy area that spreads out into a wide water body during snow-melt but reduces to a small area of water during the summer;
 - Water bodies 2 & 3 are usually result of snowmelt that dries up during the

It should be noted that all these water bodies usually have a depth of 1-2 feet during the early spring but reduce in depth during the summer.

Please note that my information is based on personal knowledge of the areas since this is my home-community and through my observation, there aren't any fish in the water bodies at. In addition, these water bodies are due to snowmelt and since Hall Beach is flat, the ponds usually dry up since they cannot drain away.

I hope this is the information you require.

Yours truly.

Jessie Innuksuk

Community Planning & Lands Administrator

Hamlet of Hall Beach