



MUNICIPAL WATER USE INSPECTION REPORT

Date: August 9th, 2006 Licensee Rep. (Name/Title): Lester Morgan / Hamlet worker

Licensee: Hall Beach Licence No.: NWB3HAL0308

WATER SUPPLY

Source(s): Water reservoir/ Sapo Lake Quantity used: Unknown

Owner:/Operator: Municipality

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Intake Facilities: A Storage Structure: A Treatment Systems: A Chemical Storage: NI

Flow Meas. Device: NI Conveyance Lines: NA Pumping Stations: A

Comments: The water reservoirs are not fenced. This needs to be addressed in the coming year. Intake facility was clean and records of chlorination and usage were noted in the building. The Sluice gate was not in operation at the time of this inspection but did appear to be in good shape and well maintained.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec./Ter.): Primary

Natural Water Body: Continuous Discharge (land or water): land

Seasonal Discharge: NA Wetlands Treatment: X Trench: None

Solid Waste: Owner/Operator: Hamlet of Hall Beach

Landfill: X Burn & Landfill: x Other: No segregation

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality: U Decant Structure: U Erosion: NI

Discharge Meas. Device: None Dyke Inspection: NA Seepages: U

Dams, Dykes: NI Freeboard: A Spills: NA

Construction: -NI O&M Plan: Unknown A&R Plan: Unknown

Periods of Discharge: NA Effluent Discharge Rate: Not monitored

Comments: During the period of the inspection only one of two cells contained effluent. The waste management area was unfenced and unsegregated. Old drums , batteries and burnable garbage were all in the same area.

FUEL STORAGE: Not inspected

Waste Oil Storage

Owner/Operator: Government of Nunavut

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: NI Water within Berms: NI Evidence of Leaks: NI

Drainage Pipes: NI Pump Station & Catchment Berm: NI

Pipeline Condition: NI Condition of Tanks: Unknown

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected Hamlet: None

INAC: Raw water, Sewage Effluent, 1 location from solid waste management area

Signs Posted SNP: Signage to be addressed at Warning: None
waste management area

Records & Reporting: pending

Geotechnical Inspection: None

Non-Compliance of Act or Licence: Sewage lagoon does not appear to have sufficient holding time for proper treatment. Lack of segregation of wastes in management area. Poor signage at waste management areas.

A. Keim

Inspector's Name

Inspector's Signature