



Appendix 2

Hazardous Materials Spill Reports

FAX TRANSMISSION

Date: September 19, 2002
Pages: 7, Including Cover
To: Mr. Shane LeBouthillier



920-2002 4319

From: Lisette Self
Director's Secretary
Environmental Protection Service
Resources, Wildlife and Economic Development
Government of the Northwest Territories
600, 5102 - 50th Avenue
Yellowknife NT X1A 3S8

Telephone: (867) 873-7654
Fax: (867) 873-0221

Subject: Spill Information for the Hamlet of Hall Beach

Hi Shane,

As requested here are the Spill Reports for Hall Beach for the last five years. If you have any questions please do not hesitate to call. Have a nice day!

Bobbi



Resources, Wildlife and
Economic Development
investing in our future

Hazardous Materials Spill Database

Environmental Protection Service of RWED

600, 5102-50th Avenue, Yellowknife, NT X1A 3S8
Phone: (867) 873-7654 Fax: (867) 873-0221

Northwest
Territories

Thursday, September 19, 2002

Sorted by Spill Number for the year(s) : 1998-2003

Page 1 of 1

Spill No	Spill Date	Region	Location	Description	Commodity	Quantity (L or kg)	Party	Source	Agency
1998139	20-Aug-98	BAF	Hall Beach	Water Supply Lake, NWS Property	Motor Oil/Transmission	12 Unknown		IRU	EPS
2000201	17-Jul-00	BAF	Hall Beach	New Arena	Heating Fuel P-50	2273-litre	Hall Beach	ST<	GN
2001234	19-Jul-01	BAF	Hall Beach	Northern Store	Heating Fuel	475	Northern Store	PL	GN
2001329	14-Oct-01	BAF	Hall Beach	Tank Farm #7	Gasoline	0	Hall Beach Co-op (POL)	ST<	GN
2002004	07-Jan-02	BAF	Hall Beach	Hall Beach Tank Farm #7	Gasoline	46	Hall Beach Co-op (POL)	ST>	GN
2002432	21-Jul-02	BAF	Hall Beach	NWS Radar Station	Jet A	14000	Nasitting Corporation (Alco Fr)	PL	EPS

Total Spills on this Report: 6

This report contains information regarding spills that were reported to the NWT 24-Hour Spill Line. The absence of information on any particular location in no way guarantees that contamination has not occurred at that location.

LEGEND

Region:	Source:	Agency:
BAF - Baffin	AIR - Aircraft	CCG - Canadian Coast Guard
DEH - Deh Cho	DRUM - Drum or Barrel	EP - Environment Canada
INU - Inuvik	MV - Marine Vessel	GN - Government of Nunavut
KEE - Keewatin	NS - Natural Seepage	GNWT - Government of the Northwest Territories
KIT - Kikriool	OTH - Other Transportation	ILA - Inuvialuit Land Administration
		INAC - Indian and Northern Affairs Canada
		NEB - National Energy Board
	PL - Pipe or Line	
	RT - Rail Train	
	SL - Sewage Lagoon	
	ST< - Storage Tank <4000 litres	
	ST> - Storage Tank >4000 litres	
	TP - Tailings Pond	
	TRU - Truck	
	UK - Unknown	
	WELL - Well Walls Flaring Boom	

867873624 AAL STATN/SPILL LINE

136 P21/01 JUL 19 '02 14:15

JUL 19 02 07:00 PM DEPT. SUSTAINABLE DEVELOPMENT 00-201



Northwest Territories

N.W.T. SPILL REPORT (Oil, Gas, Hazardous Chemicals or Other Materials)

 24-Hour Report Line
 24-00 46000 0000000000 00-201
 Phone 867-860-4033 820-8130
 Fax 867-860-4033 873-8924

A Report date and time July 19, 2002		B Date and time of spill (if known) July 16 & 17, 2000		C Original report Update no. 00-201	
D Location and map coordinates (if known) and direction (if moving) Hamlet of Hall Beach New Arena					
E Party responsible for spill Hamlet of Hall Beach					
F Product(s) spilled and estimated quantities (provide metric units/weights if possible) P50 Heating Fuel, about 500 gallons					
G Cause of spill Tank's valve was turned on by someone during the night					
H Is spill terminated? Yes	I If spill is continuing, give estimated rate No	J Is further spillage possible? Yes	K Extent of containment area (in square metres if possible) 150m ²		
L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) Depression under the fence				M Containment (natural denaturation, dikes, etc.) Depression under the fence	
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials - Pumped out about 21 drums of 45 gallon barrels. - proposed by the hamlet is to trench out the area & put new gravel on affected area					
O Do you require assistance? Yes, describe: Somewhat the cleanup is not continuing due		P Possible hazards to persons, property, or environment; eg. fire, drinking water, fish or wildlife Fish & Marine mammals			
Q Comments and/or recommendations other things to do, by Sam PIKUYAK that he says he got some oil burners to work on. - If the clean is not starts again by end of the day, I'll let J & E Enterprise Ltd to clean up the spill site. - It still needs to be pumped out & get rid of gravel & replace it with new gravel.					
Reported by Andrew Gaurag		Position, Employer, Location Wildlife Officer II DSD - Hall Beach			
Reported to Donna Kennedy		Position, Employer, Location Environmental Protection Officer - DSD HQ - Inuvik			
		Telephone 867-928-8507			
		Telephone 867-925-5909			

 FOR SPILL LINE USE ONLY
 Lead Agency
 Spill significance
 Lead Agency contact and time
 EP: Wode Komenko
 Couldnt reach
 GNC - Notified
 EP
 Is this file now closed?
 Yes

564 P01 AUG 21 '58 13:21

9.34 Nu.002 P.01



$24 \times 6^c \Delta b^c \Gamma_m^c D\sigma^b \delta^b A D^c a^{(1)} c^b P^b e D^c$

Phone/Dial DC (403) 920-8130

Fax/تلفون (403) 873-8924

Northwest
Territories

NWT 1752/QA00



N.W.T. SPILL REPORT (Oil, Gas, Hazardous Chemicals or other Materials)

24-Hour Report Line
24-Hr 867-966-2011/2012 867-966-2011
Phone/867-966-2011 (403) 820-8130
Fax/867-966-2011 (403) 873-8824

A Report date and time 21 August 1998		B Date and time of spill (if known) 20 August 1998/2040h		C Original report Update no. 1 Spill number 98-139	
D Location and map coordinates (if known) and direction (if moving) HALL BEACH - WATER SUPPLY LAKE					
E Party responsible for spill PRIVATE VEHICLE DRIVER - HALL BEACH RESIDENT					
F Product(s) spilled and estimated quantities (provide metric volumes/weights if possible) 					
G Cause of spill TRUCK DRIVEN PARTIALLY INTO LAKE					
H Is spill terminated? yes/ no		I If spill is continuing, give estimated rate 		J Is further spillage possible? yes/ no	
K Extent of contaminated area (in square metres if possible) 					
L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) 			M Containment (natural degradation, dikes, etc.) 		
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials TRUCK REMOVED - NO APPARENT RIPPED FUEL LINES OR CONTAINERS. BOOMS DEPLOYED, SORBENTS USED.					
O Do you require assistance? yes/ no			P Potential hazards to persons, property, or environment (e.g. fire, drinking water, fish or wildlife) 		
Q Comments and/or recommendations - CLEAN UP TO CONTINUE TODAY, CONTAMINATED SHORELINE TO BE REMOVED. - ALLEGED DRUNK DRIVER EXPECTED TO BE CHARGED LATER TODAY. - CONTAMINATION RESTRICTED TO ONE SMALL SECTION OF RESERVOIR. - WATER DRAIN-OFF STATION TO BE MOVED TO OPPOSITE, UP WIND SIDE OF RESERVOIR. - ARRANGEMENTS UNDERWAY FOR SAMPLING/ANALYSIS					
Reported by M. BOURQUE		Position, Employer, Location EPB - YELLOWKNIFE		Telephone (507) 669-4729	
Reported to Bleuerin		Position, Employer, Location SPILL LINE - YELLOWKNIFE		Telephone 920-8130	

+8678736924 ARCTIC ALARM STATION

553 P01/02 AUG 21 '98 08:45

FROM: FRONTEC - Facilities AWR PMT PHONE NO.: 7873884

Aug. 21 1998 09:32AM P1



N.W.T. SPILL REPORT

Oil, Gas, Hazardous Chemically or other Materials

24-Hour Report Line

Phone/Dial (403) 920-8130

Fax/Telex (403) 873-6924

98-139

A Report date and time 20 August 1998 at 22:58 hrs	B Date and time of spill (if known) 20 August 1998 at 2040 hrs	C Original report Spill number 98-139
D Location and time of spill (if known) (if not known, give location of spill) Hall Beach, NT 68°-45'-34"N and 81°-11'-41"W		
E Party responsible for spill FRONTEC Logistics Corp.		
F Product spilled and estimated quantity (include name, concentration, etc.) Fuel oil - approximately 5-10 litres		
G Cause of spill Fuel leaked from truck which was driven into a water lake (property of DND)		
H Is spill terminated? Yes ☒ No ☐	I If spill is continuing, give estimated rate N.A.	J Is further spillage possible? Yes ☐ No ☒
K Extent of contaminated area (in square metres if possible) 30' x 15' sheen on water surface		L Extent of contamination (if known) (if not known, give location of spill) N.A.
M Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) Strong wind, darkness, safety		
N Action, if any, taken or proposed to contain, recover, clean up or dispose (if possible) and contaminated materials Crew has deployed booms and solvent mats to contain slick on water surface. Will continue clean up today. Used solvent will be disposed of by burning at the site burn bin.		
O Do you require assistance? Yes ☒ No ☐	P Possible hazards to persons, property, or environment (e.g. fire, drinking water, fish or wildlife) Drinking water	
Q Comments and/or recommendations Subject truck was driven into the water by a drunk driver from the Hall Beach community. The water lake is within the property of North Warning System (NWS) Logistics Support Site and the lake supplies potable water to personnel station at this site.		FOR SPILL LINE USE ONLY Lead Agency Spill significance Lead Agency contact and time Magnus Bonfyne 0840
Reported by SM LITENIC	Position, Employer, Location Environmental Coordinator, FRONTEC Logistics Spill line - yellowknife	Telephone (613) 484-3868 Telephone 867-920-8130

98-139

BRHB Reg. Programs.

ID.8199794612

AUG 21 '98

9:34 AM 002 P.01



N.W.T. SPILL REPORT (Oil, Gas, Hazardous Chemicals or other Materials)

24-05-061506 Do-11-ADP-0-1011 Do-11-ADP-0-1011

Phone/Do-11-ADP-0-1011 (403) 820-8130

Fax/Do-11-ADP-0-1011 (403) 873-8824

A Report date and time 21/08/98 9:30am	B Date and time of spill (if known) 21/08/98 8:30pm	C Original report ☒ Update no. 98-140
D Location and map coordinates (if known) and direction of movement Hall Beach - Water Supply Lake		
E Party responsible for spill Private Vehicle Driver - Hamlet Cleaning Co.		
F Product(s) spilled and estimated quantities (provide metric volumes/weights if possible) Approx. 12L total - 10W30 Motor Oil, Transmission Fluid, gasoline		
G Cause of spill Pick-up Truck Driven into Lake - Accident		
H Is spill terminated? ☒ Yes	I If spill is continuing, give estimated rate ☐ Yes ☐ No	J Is further spillage possible? ☐ Yes ☒ No
K Extent of contaminated area (in square metres if possible) 1/2 mile along shore		
L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) Wind + Darkness (Surface of materials)		
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials Cleaned up majority of spill. Check to be done this morning. Taken to dump for disposal. Alternate Water Supply being arranged. Water delivery ceased until testing can be conducted.		
O Do you require assistance? ☐ No ☒ Yes describe:	P Possible hazards to persons, property, or environment, eg: fire, drinking water, fish or wildlife None	
Q Comments and/or recommendations Response as to testing parameters needed. Also identification of proper Laboratory Services Update to be provided by SAC at Hamlet Office.		
Reported by Nicole Ritchie Reported to Bricker	Institution, Employer, Location Health Officer - BRHSSB Paulson, Employer, Location Spill Line - Yellowknife	

FOR SPILL LINE USE ONLY

 Lead Agency EP
 Spill significance
 Lead Agency contact and time
 Tagmus Bank
 0840

 Tagmus Bank
 0840

 Is this file now closed?
☐ Yes ☐ No

 Telephone
 867-979-7654
 867-920-8130