

Municipality of Kimmirut

Box 120, Kimmirut, NU X0A 0N0 Ph. (867) 939-2247 Fx. (867) 939-2045

November 04, 2005

Nunavut Water Board P.O. Box 119 Gjoa Haven, Nu XOB 1JO

Attention: Phyllis Beaulieu

Manager of Licencing

Dear Phyllis:

I wish to acknowledge receipt of your letter dated October 31, 2005 and thank you for reminding me that our 2004 report is overdue.

Our 2004 Annual Report is enclosed, Item A and B in your above letter I believe have been addressed in this report; however, should you wish any additional information please contact me.

Sincerely,

Cecil O. Marshall

Senior Administrative Officer

Cicil O. Marshalf

Nunavut Water Board of

Chinia Pasisa

DAACS RETAIN TUVARUM

SCANNED

NOV 2 4 2005

MEF. #15110411483Kith 2004 Annual Report

ANNUAL REPORT FOR THE HAMLET OF KIMMIRUT

-1147		-24.	and the same of th	1. 1	And the second of the second s	V WARREN CONTRACTOR CO
	and the Control of th		allen	-		
a li	st of unauthorized	discharges an	d summary of	follow-up ac	etion taken;	
	hu vu n 200p	16 m	nnau y fin	thorize	d disc	Aug
a su	unmary of any abar	adanmant	*************************************			
an (outline of any work Nast Candoned	anticipated f	restoration wor the next ye	ork complete ar;	ed during the ye	ear and
an (mmary of any studior reclamation, and	ies requested la brief descr	by the Board iption of any	that relate to	waste disposal	
asu use urt F.	mmary of any studior reclamation, and	ies requested la brief descriand Mainte	by the Board iption of any nance Manu	that relate to future studies	waste disposal	

ANNUAL REPORT FOR THE HAMLET OF KIMMIRUT

vi	ii. any other details on water use or waste disposal requested by the Board by November
	1st of the year being reported; and
	you letter dated October 31 2005 refus to the
	development of a Monitorine Than then has
	not bun done as we never heard learn the
	NWB in accordance with your little of
	argust 21 2004, Jaking the server sende
	is still a proplem.
ix.	updates or revisions to the approved Operation and Maintenance Plans.
	Mon that I am awar of
ADDI	MONAL INFORMATION THAT THE HAMLET DEEMS USEFUL:
	He work was done on the road leading
	to the new swage and solid waite
	disposal sites in hoop by Community
	and government burges.
FOLL	OW-UP REGARDING INSPECTION/COMPLIANCE CONCERNS:
	I believe we are in total compliance
	so far as the operation show solid
	waste site and surge disposal site
	is consumed at the primet time.
	obtaining and testing of sewage sample
	The second secon
	Almany a problem but now are arenared
	The severes This rose and now to
	summer of property on to an prepared

iv. No major work was required on the water supply system during 2004. Minor repairs were carried out on the power unit in the truck fill station and the required signage was erected at the water lake near the truck fill station.

At our Waste Disposal Facilities we completed the following work:

- (a) All debris of any description along the road leading to the water lake was removed and taken to the dump site.
- (b) All full or partially full 45 gallon drums in the dump site or along the road leading to the water lake had all missing bungs replaced and were moved to a level site within the dump site.
- (c) All batteries in the dump site were removed to our Parking Garage lot to await shipment south for proper disposal.
- (d) The sewage disposal site was moved approximately 30 meters south closer to the edge of the mountain as required and a granular material burm was constructed to direct the flow.
- (e) The bagged sewage area was filled and covered over with a depth of approximately 2 feet of granular Material.
- (f) The general solid waste site was bulldozed and covered over with granular material. This did not include one large area of scrap metal, consisting of mostly scrap vehicles or equipment.
- (g) The main burning site was leveled with the bulldozer and covered with 8 to 12 inches of granular material.
- (h) To my knowledge we did not accept any hazardous waste from commercial sources in 2004.