

FIGURE 7
HAMLET OF KUGLUKTUK
SEWAGE TREATMENT FACILITY &
SOLID WASTE MANAGEMENT FACILITY
DETAILED DESIGN - MARCH 2007

CONTAMINATED SOIL AND
WASTE OIL STORAGE AREA


- Legend**
- TEST PIT LOCATION
 - GROUNDWATER SAMPLE LOCATION
 - SOIL SAMPLE LOCATION
 - EXISTING GEOTEXTILE LINER
 - EXISTING CONTOURS (m amsl) by Ollerhead & Associates Ltd. Contour interval 0.25m

Image Source: © Copyright 2002 DigitalGlobe Inc., All Rights Reserved.

Image Platform: Quick Bird (Satellite)

Image Acquisition: 01 July 2002

Spatial Resolution: 0.6m



1:500
March 2007
Project Number: FE009754
Prepared by: C. Reynolds

Projection: UTM Zone 15
Datum: NAD83
Verified by: J. Walls

