



MUNICIPAL WATER USE INSPECTION FORM

DATE: Aug 12/09 COMPANY REP.: Richard Tungilik
LICENSEE: Hamlet of Repulse Bay LICENCE #: Unlicensed

WATER SUPPLY

Source (s): Mealy Muktungay Lake Quantity Used (to date):
Owner/Operator: (estimate or actual)

Indicate: A. - Acceptable U. - Unacceptable N/A - Not Applicable

Intake Facilities: A Storage Structure NA Treatment Systems A Chem. Storage NI
Flow Meas. Device A Convey. Lines NA Pumping Stations A

Comments: The pump house is clean & well maintained with consistent record keeping. I advised
Richard that for a total chlorine concentration should be measured on Saturday & Sunday.

WASTE DISPOSAL

Sewage Sewage Treatment System (primary, secondary or tertiary) 2°
Natural Water body ✓ Continuous Discharge (land or water) ✓
Seasonal Discharge ✓ Wetlands Treatment Some Trench ✓
Solid Waste: Owner/Operator: Hamlet
Landfill ✓ Burn & Landfill ✓ Other ✓

Indicate: A. - Acceptable U. - Unacceptable N/A - Not Applicable

Disch. Quality Sampled Decant Structure NA Erosion NA
Disch. Meas. Dev. NA Dyke Inspection NA Seepages NA
Dams, Dykes NA Freeboard NA Spills NA
Construction NA O & M Plan None A & R Plan None

Periods of Discharge: ✓ Effluent Discharge Rate: ✓

Comments: The Hamlet has done a lot of work cleaning the old landfill. While still remains
but it is not a problem. The Hamlet has also begun cutting up bulky material
which can be landfilled. The Hamlet should be commended for its efforts. There is
a long system of ponds is in place to treat sewage effluent. At the sample site the effluent

FUEL STORAGE Owner: Hamlet Operator: Hamlet Condition of Tanks ✓
Berms & Liners NI Water within berm: NI Evidence of Leaks: NI
Drainage Pipes NI Pump Station and Catchment Berm NI
Pipeline Condition ✓ Not Applicable: ✓

SURVEILLANCE NETWORK PROGRAM

Samples Collected: (Hamlet) None
(DIAND) COR-1, COR-3
Signs Posted: SNP No Monitoring Program in Place Warning ✓
Record & Reporting Monthly water sampling sent to Eureka Inlet.

Geotechnical Inspection: None

Non-Compliance of Act or Licence: The Hamlet does not currently possess the Water Licence
it requires under the WWSRA. The Hamlet should take the necessary steps required
to get licensed. However the Hamlet deserves to be commended for the efforts it has made
to decommission the old dump and clean up the general area around town. Hopefully
the Hamlet will continue its efforts to comply with the Act. Page 2 attached Yes ✓ No ✓

Acting Foreman
Licensee Representatives Title
Richard Tungilik
Licensee Representatives Signature

Scott Stewart
Inspectors Name
Scott Stewart
Inspectors Signature



WATER USE INSPECTION REPORT

(continued)

Date: Aug 12/04

Reynold Bay
Licence #: Unlicensed

General Comments: (Continued)

sewage effluent is bright green in colour at the final pond before discharge into the ocean but there is no odour of sewage. The Hamlet may eventually require a more effective treatment system to meet the higher effluent standards required to meet the requirements of the Fisheries Act.

The Hamlet has prepared a number of waste oil barrels to be shipped south. Once the NAC has installed a waste oil burner it will be used to dispose of the Hamlet's waste oil. The stockpiled barrels are to be shipped out this fall. Island has informed us that the Hamlet plans to clean-up the area downstream of the sewage lagoon. I would also like to see the garbage around the lagoon cleaned up. Keep up the good work.

INTERNAL	
PC	ap
MA	
FO	
LA	
BS	
BT	
TA	
TA2	
RC	
ED	
CH	
BRD	
EXT.	

Nunavut Water
Board
NOV 26 2004
Public Registry

Scott Stewart

Water Inspector