



WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

|   |                               |
|---|-------------------------------|
| Licensee  | Licensee Representative       |
| Hamlet of Naujaat   | Kevin Tegumiar                |
| Licence No. / Expiry  | Representative's Title        |
| 3BM-NAU2126/January 26 <sup>th</sup> , 2026   | Senior Administrative Officer |
| Land / Other Authorizations   | Land / Other Authorizations   |
| --  | --                            |
| Date of Inspection  | Inspector                     |
| August 18 <sup>th</sup> 2020  | Atuat Shouldice               |
| Activities Inspected  |                               |
| <div><input type="checkbox"/> Camp<input type="checkbox"/> Drilling<input type="checkbox"/> Mining<input type="checkbox"/> Construction<input type="checkbox"/> Reclamation<input type="checkbox"/> Fuel Storage</div> <div><input type="checkbox"/> Roads/Hauling<input checked="" type="checkbox"/> Other: Waste Disposal Facility<input checked="" type="checkbox"/> Other: Water Treatment Facility</div> |                               |

|   |  |  |   |
|---|--|--|---|
| SECTION 1   | <input checked="" type="checkbox"/> Comments (s. 1_) | <input type="checkbox"/> Non-Compliance with Act or Licence (s. _)     | <input type="checkbox"/> Action Required (s. _)     |
| <b>Background</b> <p>Naujaat is a Hamlet at the north end of Roes Welcome Sound which separates Southampton Island from the mainland. The Hamlet is located exactly on the Arctic Circle.</p> <b>Inspector's Statement</b> <p>On August 18th 2020, a water licence inspection was conducted of water licence no. 3BM-NAU2126 (formally 3BM-REP1520) issued to the Hamlet for the use of water and deposit of waste as it relates to municipal undertakings. The inspection was conducted to ensure compliance with applicable terms and conditions of the licence.</p> <p>This report is written with the observation from the August 18<sup>th</sup>, 2020 inspection and the conditions of the current licence no. 3BM-NAU2126.</p> <b>Observation</b> <ol style="list-style-type: none"><li>Fresh water is obtained from Nuvik Luktujuk Lake, as approved by PART C item 1.</li><li>All sewage is directed to the Sewage Disposal Facility which utilizes wetland treatment. Work is scheduled to begin on the sewage lagoon upgrade next summer (2021-2022).</li><li>Concerns noted in the 2019 report regarding the landfill's south berm and hazardous waste storage for battery have not yet been resolved.</li><li>The Hamlet has begun segregates hazardous waste in 2019 (e.g.: oil, glycol, batteries, contaminated soil and propane cylinders) with the intentions of shipping the materials south for appropriate treatment once funds is available.</li><li>The Landfill is very full, once capacity is reached proper segregation of materials will be limited.</li><li>Many spills have occurred within the Hamlet between 2018-2020. Numerous bags of contaminated soil are being stored Hazardous waste storage area.</li></ol> |  |  |   |
| SECTION 2   | <input type="checkbox"/> Comments                    | <input checked="" type="checkbox"/> Non-Compliance with Act or Licence | <input type="checkbox"/> Action Required            |
| <b>Concerns related to Water Licence no. 3BM-NAU2126;</b> <p>PART D Item 6: Failure to maintain the landfill to the satisfaction of the Inspector.</p> <p>PART D Item 10: Failure to maintain hazardous waste storage to the satisfaction of the Inspector.</p>   |  |  |   |
| SECTION 3   | <input type="checkbox"/> Comments                    | <input type="checkbox"/> Non-Compliance with Act or Licence            | <input checked="" type="checkbox"/> Action Required |
| <div><div>— The Hamlet has made improvements in the segregation of waste and hazardous waste at the Landfill with the limited space they have. Future plans for the new landfill space should be considered a priority.</div><div>— The Hamlet shall submit a plan to the Inspector by June 1<sup>st</sup> 2021, as to how they will repair the breached south berm at the Landfill and maintain the battery storage area. This plan shall include a brief summary of work and completion date.</div></div>   |  |  |   |

|                            |                               |
|----------------------------|-------------------------------|
| Licensee or Representative | Inspector's Name              |
| Kevin Tegumiar             | Atuat Shouldice               |
| Signature                  | Signature                     |
|                            | Sent Electronically           |
| Date                       | Date                          |
|                            | January 15 <sup>th</sup> 2021 |

CC:           Licensing Department, NWB  
              Justin Hack, Manager of Field Operations, CIRNAC  
              Megan Lusty, Municipal Works, CGS



|                            |                                      |                             |                            |
|----------------------------|--------------------------------------|-----------------------------|----------------------------|
| Date:<br>August 18th, 2020 | Authorization Number:<br>3BM-NAU2126 | Camera/Model:<br>Samsung S9 | Inspector<br>RMO Shouldice |
| Photo #<br>1               |                                      | Location:<br>Landfill       |                            |



|                                |
|--------------------------------|
| Description                    |
| Bulk storage North of Landfill |

|              |                       |
|--------------|-----------------------|
| Photo #<br>2 | Location:<br>Landfill |
|--------------|-----------------------|



|  |
|--|
| Description                                    |
| Battery collection area North of bulk storage. |





| Photo #  | Location (NAD 83 DD MM SS.SS)              |
|--|--|
| 3  | Waste Oil and contaminated storage laydown |
|  |  |
| Description  |  |
| Contaminated Soil storage.   |  |