

Appendix B: Photographs of the Project area



Photo 15 Stream reach downstream of CRS-4 crossing with large snowpack still present; north aspect.



Photo 16 North of CRS-4 crossing stake located at Km 4.4 of the proposed access road route, note snowpack and boulders; south aspect.



Photo 17 Large snowpack along stream, and stream substrate downstream of CRS-4 crossing; southeast aspect




Photo 18 CRS-5 crossing located at Km 5.0 of the proposed access road route, note snow cover and bedrock ridges; southeast aspect.

Appendix B: Photographs of the Project area



Photo 19 Stream reach upstream of CRS-5 crossing with potential barrier to fish passage, northeast aspect.



Photo 20 Stream reach downstream of CRS-5 crossing, note snow cover, vegetated valley bottom and bedrock ridges to east and west; south aspect.



Photo 21 Proposed access road route near Km 5.7 with route stake and ATV trail, note terrain and standing water; east aspect.




Photo 22 CRS-6 crossing stake located at Km 6.2 of the proposed access road route, note lack of defined channel at crossing and existing ATV trail in background; north aspect.