



View from Washout of North west corner of solid waste facility down to Pangnirtung Fiord and tidal area. Note contaminated standing water



Close up



facility.

Wash out at the solid waste



View of Pangnirtung Hamlet staff pumping out reservoir. Note 5 gallon gas can beside pump.



View of fence around reservoir, not extending to ground level.





View of sludge bags mixed with commercial fish wastes / piled beside and uncovered.



View of commercial fish wastes, uncovered, obviously overflowing. Note sludge bags in background.



Larger view of commercial fish wastes and sewage sludge.