

Jul-04-2002 01:00PM From:PETROLEUM PRODUCTS DIVISION POND INLET 4857 000 7811

7-234 P.002/002 P-140



N.W.T. SPILL REPORT

24 Hour Report Line
Phone: (403) 920-8131
Fax: (403) 873-6824

A Report date and time JULY 4/02 9:00 AM	B Date and time of spill (if known) JULY 4 9:10 A.M.	C Spill number 02-411
--	--	---------------------------------

D Location and map coordinates of property and location of spill:
PANGNIRTUNG AIRPORT - AIRSIDE AREA

E Party responsible for spill:
PANGNIRTUNG CO-OP

F Product(s) spilled and estimated quantities (provide name and volume/weight if possible)
JET A1 APPROX 15-20 litres

G Cause of spill:
EQUIPMENT

H Is spill contained? ☒ Yes ☐ No	I Is spill contained, deep contained, etc. ☒ Yes ☐ No	J Is further spillage possible? ☐ Yes ☒ No	K Edge of contained area (in square metres if possible) 2 METERS
--	---	--	--

L Factors affecting spill or recovery (weather conditions, terrain, time of day, etc.)
Area cleaned up by loader + disposed of. Replaced contaminated soil with clean soil.

M Containment (natural depression, dykes, etc.)
Area cleaned up by loader + disposed of. Replaced contaminated soil with clean soil.

N Action, if any, taken or proposed to contain, remove, clean up or dispose of product(s) and contaminated materials
Area cleaned up by loader + disposed of. Replaced contaminated soil with clean soil.

O Do you require assistance?
☒ Yes ☐ No

P Possible exposure to persons, property, or environment; or fire, drinking water, fish or wildlife
Area affected was cleaned up by loader.

Q Comments and/or recommendations:
Area affected was cleaned up by loader.

FOR SPILL LINE USE ONLY

Lead Agency: **GNW**
Soil significance: **AV**
Lead Agency contact and time: **07/05/02 08:33**
Robert ENO
ep. ANNE Wilson

INTERNAL	
FO	00
LA	
OM	
TA	
BS	
ST	
ED	
GEO	
BRD	
EXT.	

Reported by: GLENN	Position, Employer, Location: RELIEF MANAGER	Telephone: 867-473-8970
Reported to: RELIEF MANAGER	Position, Employer, Location: RELIEF MANAGER	Telephone: 867-473-8970