



Indian and Northern
Affairs Canada

Affaires indiennes
et du Nord Canada

Box 100

Qaluit, NT. X0A 0H0

Your file Votre référence

Our file Notre référence

B9545-5-N5L4-0572

August 15, 1996

Mr. Jake Anaviapik
Senior Administrative Officer
Municipality of Pond Inlet
Pond Inlet, NT, X0A 0S0

INDIAN AND NORTHERN
AFFAIRS — CANADA
N.W.T. REGION

AUG 19 1996

WATER RESOURCES
DIVISION
YELLOWKNIFE, NT

Dear Mr. Anaviapik:

RE: RECENT WATER LICENCE INSPECTION - JULY 22, 1996

Attached for your information and records is a copy of a Water Licence Inspection Report prepared by Mr. Peter Kusugak, an Inspector designated under the Northwest Territories Waters Act.

As the report indicated there are several questions that need to be answered as a result of the inspection with respect to the operation and utilization of the new Waste Disposal Site. They are as follows:

- 1) When will the new site become operational?
- 2) How will the water inside the waste oil berm be drained?
- 3) When will the Hazardous Waste Sealift container be in place for the storage of the Hazardous Wastes?

Please provide the answers to these questions to this office at your earliest convenience. Should you have any questions regarding this report or the status of the Hamlet's Water Licence Application, please feel free to contact the undersigned at (819) 979-4405 at any time.

Sincerely,

Dan Elliott
District Manager
Nunavut District

c.c. Municipal Coordinator, Water Resources Division - DIAND
Nunavut Water Board

Canada



MUNICIPAL WATER USE INSPECTION FORM

DATE: JULY 22, 1996 COMPANY REP: JAYKO ANAVIARIK
LICENSEE: HAMLET OF POND INLET LICENCE #: N5L4-0572 (APPLICABLE PROCESS)

WATER SUPPLY

Source (s): RESERVOIR Quantity Used (to date): _____
Owner/Operator: GNWT / HAMLET (estimate or actual)

Indicate: A - Acceptable U. - Unacceptable N/A - Not Applicable

Intake Facilities: A Storage Structure _____ Treatment Systems A Chem. Storage A
Flow Meas. Device A Convey. Lines _____ Pumping Stations A

Comments: AREA AROUND TRUCK FILL STATION IN ACCEPTABLE CONDITION
NO CONCERNS NOTED.

WASTE DISPOSAL

Sewage Sewage Treatment System (primary, secondary or tertiary) PRIMARY

Natural Water body _____ Continuous Discharge (land or water) OVER LAND TO OCEAN

Seasonal Discharge _____ Wetlands Treatment _____ Trench _____

Solid Waste: Owner/Operator: GNWT / HAMLET

Landfill _____ Burn & Landfill _____ Other _____

Indicate: A - Acceptable U. - Unacceptable N/A - Not Applicable

Disch. Quality _____ Decant Structure _____ Erosion _____

Disch. Meas. Dev. _____ Dyke Inspection _____ Seepages _____

Dams, Dykes _____ Freeboard _____ Spills _____

Construction _____ O & M Plan _____ A & R Plan _____

Periods of Discharge: _____ Effluent Discharge Rate: VARIOUS

Comments: _____

FUEL STORAGE Owner: PUL Operator CO-OP Condition of Tanks GOOD.

Berms & Liners GOOD Water within berm: NO Evidence of Leaks: NO

Drainage Pipes YES Pump Station and Catchment Berm _____

Pipeline Condition GOOD Not Applicable: X

SURVEILLANCE NETWORK PROGRAM

Samples Collected: _____ (Hamlet)

NO SAMPLE TAKEN RAW WATER FROM RESERVOIR & FROM SALMON CREEK

Signs Posted: SNP _____ Warning PRESENT

Record & Reporting _____

Geotechnical Inspection: _____

Non-Compliance of Act or Licence: HAMLET HAS APPLIED FOR WATER LICENCE

Page 2 attached Yes ✓ No _____

NOT AVAILABLE
Licensee Representatives Title

PETER KUSUGAK
Inspectors Name

[Signature]
Inspectors Signature

Licensee Representatives Signature



WATER USE INSPECTION REPORT (continued)

Date: JULY 22

Licence #: NS24-0572

General Comments: (Continued)

WASTE DISPOSAL:

NO CHANGES HAVE OCCURED SINCE LAST YEAR.
STILL NOT COVERED WITH GRANULAR MATERIAL
REGULARLY. THE WASTE IS STILL BLOWING INTO
TOWN AREA.

SEWAGE DISPOSAL:

NO CHANGES ALSO HAVE OCCURED IN THIS AREA
BUT STILL BEING USED TILL THE NEW ONE
IS FINISHED.

NEW WASTE & SEWAGE DISPOSAL AREA:

ROAD TO THE NEW SITE IS COMPLETED. FENCING IS
ALSO UP IN THE AREA.
SIGNS WHERE WASTE ARE TO GO ARE UP - WASTE IN
CONSTRUCTION, METAL WASTE, SEWAGE, AND HAZARDOUS WASTE
ALSO AN AREA FOR WASTE OIL.
THE BERM FOR THE SEWAGE IS UP BUT FINAL
GRADE IS STILL NEEDED, PLUS A PAD FOR SEWAGE TRUCK
TO BACK UP ON FOR DISPOSAL. STILL HAD TO BE PUT IN.
SEALIFT CONTAINER FOR HAZARDOUS MATERIAL STILL NEEDS
TO BE PUT IN AS PLANNED.

Cont'd...

Water Inspector



WATER USE INSPECTION REPORT
(continued)

Date: July 22

Licence #: N5L4-0572

General Comments: (Continued)

WATER LAKE & INTAKE FACILITY

AREA AROUND THE LAKE WAS FOUND VERY CLEAN
AND ACCEPTABLE. AROUND THE FACILITY (INTAKE)
WAS * CLEAN - NO CONCERNS NOTED.

PICTURES OF THE ABOVE WERE TAKEN.

WATER AND SEWAGE SAMPLES WERE NOT TAKEN
DURING THE INSPECTION

Water Inspector