

**C.O.C.: G35670**

**REPORT No. B13-23734**

**Report To:**

**Municipality of Qikiqtarjuaq**

P.O. Box 4,

Qikiqtarjuaq Nunavut

**Attention:** Philip Sanquaya

**Caduceon Environmental Laboratories**

2378 Holly Lane

Ottawa Ontario K1V 7P1

Tel: 613-526-0123

Fax: 613-526-1244

DATE RECEIVED: 10-Sep-13

JOB/PROJECT NO.:


DATE REPORTED: 13-Sep-13

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO.

			<b>Client I.D.</b>		Raw Drinking Water - Turbidity			
			<b>Sample I.D.</b>		B13-23734-1			
			<b>Date Collected</b>		05-Sep-13			
<b>Parameter</b>	<b>Units</b>	<b>M.D.L.</b>	<b>Reference Method</b>	<b>Date/Site Analyzed</b>				
Turbidity	NTU	0.1	SM 2130	13-Sep-13/O	0.9			



Gord Murphy

Lab Supervisor

M.D.L. = Method Detection Limit

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from Caduceon Environmental Laboratories.