

**WATER LICENCE INSPECTION FORM**☐ Original
☒ Follow-Up Report

Licensee	Licensee Representative
3BM-RAN2025	Darren Flynn
Licence No. / Expiry	Representative's Title
December 20, 2025	Senior Administrative Officer
Land Authorization No. / Expiry	Land Authorization Expiry
NA	NA
Date of Inspection	Inspector
September 21, 2022	WRO K AMSEL
Activities Inspected	
<input type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage	
<input type="checkbox"/> Roads/Hauling <input checked="" type="checkbox"/> Other: Solid Waste Disposal Facility <input type="checkbox"/> Other:	

SECTION 1	<input checked="" type="checkbox"/> Comments (s.____)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.____)	<input type="checkbox"/> Action Required (s.____)
<p>On August 18, 2022 Water Resource Officer Kyle Amsel (Inspector) of Crown-Indigenous Relations and Northern Affairs Canada, (CIRNAC) conducted an Inspection of Water Licence 3BM-RAN2025 (Licence). The Licence is issued to the Hamlet of Rankin Inlet for the operation of a solid waste disposal facility (Facility). The Inspection was conducted to ensure compliance with the <i>Nunavut Waters and Nunavut Surface Rights Tribunal Act</i> (Act) and the terms and conditions of the Licence.</p> <p>On September 21, 2022 the Inspector accompanied by Public Works Director Troy Aksalnik attended the Facilities to move the Monitoring Point Location RAN-2.</p> <p>The Inspector found the original location of RAN-2 was no longer appropriate to meet monitoring objectives. Part H Item 1 states for RAN-2 "Runoff from the Old Landfill". The new location selected had active flow during the inspection and during installation of the signage. RAN-2 is now situated at N62° 47' 57.7" W92° 04' 33.4". (photo 1)</p> <p>Observations</p> <ol style="list-style-type: none">1. The Licensee has installed the necessary signage satisfying Part B Item 5 of the Licence.2. Capping has been placed on portions of the household garbage areas of the Facility. (photo 2)			
SECTION 2	<input type="checkbox"/> Comments (s.____)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input type="checkbox"/> Action Required (s.____)
No items of Non-Compliance			

Licensee or Representative	Inspector's Name
Darren Flynn	K Amsel
Signature	Signature
Date	Date
October 11, 2022	October 11, 2022

Office Use Only: Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---