

WATER USE INSPECTION REPORT

Date: July 04,2009	Licensee Rep. (Name/Title): Duncan Walker- Senior Administrative Officer
Licensee: Municipality of Resolute Bay	Licence No.: 3BM-RES Unlicensed

WATER SUPPLY

Source(s): Water Lake	Quantity used: Unknown
Owner:/Operator: Government of Nunavut	Local service contract -

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Intake Facilities: NA	Storage Structure: NA	Treatment Systems: NI	Chemical Storage: NI
Flow Meas. Device: NI	Conveyance Lines: NI	Pumping Stations: NI	Screen : NI

Comments: The municipality remains without a water license. The Municipality retains the responsibility for solid waste management within community. The Government of Nunavut (GN) also remains unlicensed and is responsible for the municipal water and waste water services in the community through a local service contract.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.):None-Sewage discharged directly to ocean

Natural Water Body: No	Continuous Discharge (land or water): water (ocean)		
Seasonal Discharge: N/A	Wetlands Treatment: None	Trench: None	

Solid Waste: Waste not segregated, Hazardous wastes noted in Municipal land fill.

Owner/Operator: Hamlet of Resolute Bay

Landfill: Old one in use.	Burn & Landfill: U	Other: Bulk metals area
---------------------------	--------------------	-------------------------

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality: U	Decant Structure: NA	Erosion: NI
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: U
Dams, Dykes: NA	Freeboard: NA	Spills: 08-560 closed
Construction: NA	O&M Plan: U (none submitted)	A&R Plan: U
Periods of Discharge: Con.	Effluent Discharge Rate: Unknown	

Comments: Municipal metal dump is un-segregated and hazardous materials including batteries etc were noted during the inspection. The Burn and bury Municipal waste are is un-controlled. No fencing exists. As the facility is open to the public and contractors items have been deposited such as propane cylinders, oil filters, insulation, paint cans etc. Such items were noted during the inspection.

FUEL STORAGE: Tank farm has a large quantity of contaminated water within the bermed area.

Waste Oil Storage: None **Owner/Operator:** Government of Nunavut

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: U- obvious tears noted	Water within Berms: U	Evidence of Leaks: NI
Drainage Pipes: U	Pump Station & Catchments Berm: NI	
Pipeline Condition: U	Condition of Tanks: Old tanks decommissioned, Rips in liner noted in Containment area. Suction hose noted on berm.	

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected		Owner /Operator: No samples have been submitted
0		INAC: No seepages were noted from the waste management areas
Signs Posted	SNP: none	Warning: 1 at effluent discharge pipe
Records & Reporting: No records of water usage, waste discharge.		
Geotechnical Inspection: N/A		

Non-Compliance of Act or Licence: The Municipality has a newly constructed land fill that remains unused pending a request for further information or a resubmission of the application for a water license by the Nunavut Water Board. The municipality remains unlicensed and in contravention of the Nunavut water and Nunavut Surface Right Tribunal Act.