



WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

Licensee	Licensee Representative
Hamlet of Whale Cove	Ian Copland
Licence No. / Expiry	Representative's Title
3BM-WHA1520	Senior Administrative Officer
Land / Other Authorizations	Land / Other Authorizations
	--
Date of Inspection	Inspector
July 11 th 2017	Atuat Shouldice
Activities Inspected	
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
	<input type="checkbox"/> Construction
	<input type="checkbox"/> Other:
	<input type="checkbox"/> Reclamation
	<input checked="" type="checkbox"/> Fuel Storage
	<input checked="" type="checkbox"/> Other: Spill no. 17-103

SECTION 1	<input checked="" type="checkbox"/> Comments (s.1)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.)	<input type="checkbox"/> Action Required (s.)
Summary			
On July 11 th , 2017 Indigenous and Northern Affairs Canada’s Water Resource Officer, Atuat Shouldice completed an annual Community inspection of the hamlet of Rankin Inlet permit 3BM-WHA1520. The inspection was conducted with Megan Lusty, Municipal Planning Engineer with the Government of Nunavut.			
SECTION 2	<input checked="" type="checkbox"/> Comments (s.)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input type="checkbox"/> Action Required (s.)
Observations			
LANDFILL			
The Hamlet has completed the landfill fencing repairs that were requested in 2016. Cross pieces added to the center of the posts and this upgrade has allowed the fence to withstand high winds and high snow load during the winter. Efforts at segregating bulky items from domestic waste have been initiated. With limited equipment this is an on-going process and the inspector encourages the Hamlet to continue this work.			
SEWAGE			
Upgrades to the sewage lagoon initiated in 2016 have been completed. These upgrades have ensured that no leaching was noted around the perimeter of the lagoon.			
WATER			
Water is trucked in to community and is metered during delivery. Records have been provided to the inspector for review.			
Hazardous waste			
Discarded batteries are stored in a seacan next to the Hamlet storage garage. The Hamlet is encouraged to continue segregating hazardous waste and storing this waste in a manner that will prevent waste from entering fresh water.			
SECTION 3	<input type="checkbox"/> Comments (s.)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s.)	<input checked="" type="checkbox"/> Action Required (s.3)
The Hamlet of Whale Cove has been making significant progress in meeting the terms and conditions of its water license.			
For the summer of 2018, the inspector requests that work be done on the following:			
<div>1. The Hamlet should inform the community about how hazardous waste is being collected and segregated at the landfill. It should be clear where residents are to drop off the various types of waste.</div> <div>2. Waste oil drums should be palletised and capped so they do not leach in to environment.</div>			

Licensee or Representative	Inspector's Name
	WRO A Shouldice
Signature	Signature
Date	Date
	4/19/2018

Office Use Only:	Follow-up report to be issued by Inspector	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
------------------	--	---

cc. Erik Allain, Manager Field Operations, INAC