



WATER LICENCE INSPECTION FORM

☒ Original  
☐ Follow-Up Report

Licensee	Licensee Representative				
Hamlet of Whale Cove	Brain Fleming				
Licence No. / Expiry	Representative's Title				
3BM-WHA2126/ March 25, 2026	Senior Administrative Officer				
Date of Inspection	Inspector				
August 24 <sup>th</sup> 2021	Atuat Shouldice				
Activities Inspected					
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Fuel Storage
<input type="checkbox"/> Roads/Hauling	<input checked="" type="checkbox"/> Other: Waste Disposal Facility		<input checked="" type="checkbox"/> Other: Water Treatment Facility		

SECTION 1	<input checked="" type="checkbox"/> Comments (s._1_)	<input type="checkbox"/> Non-Compliance with Act or Licence (s._)	<input type="checkbox"/> Action Required (s._)
<b>Background</b> On August 24th , 2021, a regularly scheduled inspection was conducted of the Nunavut Water Board (NWB) water licence no. 3BM-WHA2126 issued to the Hamlet of Whale Cove. The inspection was conducted to ensure compliance with applicable terms and conditions of the licence. Community and Government Services representatives Matthew Hewey accompanied the Inspector on the inspection.			
<b>Observation</b> <div><div>1. The 2020 annual report was available for review as required by PART B item 1.</div><div>2. Appropriate signage was observed at the monitoring stations, as required by PART B item 6.</div><div>3. Fresh water is obtained from Fish Lake, as required by PART C item 1.</div><div>4. The total water used in 2020, according to the Annual Report was 16,439.900 m³.</div><div>5. From Fish Lake the water is pumped in to a temporary filtration system called a Filterboxx then put in water trucks and delivered to the community.</div><div>6. Water use number are calculated from truck fill totals.</div><div>7. Sewage is directed to the Sewage Lagoon from truck. Prior to discharge from the Lagoon samples are collected at WHA-3 and provided to the Inspector. Discharge from the Lagoon commenced on July 30<sup>th</sup> 2021.</div><div>8. Samples were collected at WHA-3 and provided to the Inspector in 2020 and 2021.</div><div>9. The segregated and collection of hazardous waste (e.g.: oil, batteries, and propane) requires improvement.</div><div>10. The Hamlet has been working on segregating bulk items within the Landfill.</div></div>			


[Click here to enter text.](#)

SECTION 2	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input checked="" type="checkbox"/> Action Required
<b>Action Required</b> <div><div>— All outstanding Annual reports were submitted as requested by the Inspector in the 2020 inspection report [2020-KIV05-AS] 3BM-WHA1520.</div><div>— During the writing of this report a new water licence was issued to the Hamlet of Whale Cove, 3BM-WHA2126.</div><div>— The Hamlet will submit a letter, as to how they will begin the collection and storage of hazardous waste for 2021/2022 season. This letter will be submit to the Inspector by November 29<sup>th</sup>, 2021 as a commitment to improving these efforts.</div></div>			

Licensee or Representative	Inspector's Name
Brain Fleming	Atuat Shouldice
Signature	Signature
	Sent Electronically
Date	Date
	October 26 <sup>th</sup> , 2021

CC:                   Licensing Department, NWB  
                          Manager of Field Operations, CIRNAC  
                          Sarah Collins, Municipal Works, CGS



Date:	Authorization Number:	Camera/Model:	Inspector:
August 24th, 2021	3BM-WHA2126	Samsung S9	RMO Shouldice
Photo #:		Location:	
1		Landfill	
			
Description:			
Road dividing domestic waste (right) and bulk waste (left), image facing North-West.			





Date:	Authorization Number:	Camera/Model:	Inspector:
August 24th, 2021	3BM-WHA2126	Samsung S9	RMO Shouldice
Photo #:		Location:	
2		Landfill	
			
Description:			
Contact water pond down hill of bulk fuel storage, image facing West.			



Date:	Authorization Number:	Camera/Model:	Inspector:
August 24th, 2021	3BM-WHA2126	Samsung S9	RMO Shouldice
Photo #:		Location:	
3		Landfill	
			
Description:			
Berm in image is the community Landfarm (left)			





Date:	Authorization Number:	Camera/Model:	Inspector:
August 24th, 2021	3BM-WHA2126	Samsung S9	RMO Shouldice
Photo #		Location:	
4		Sewage discharge	
			
Description:			
Sewage Lagoon			





Date:	Authorization Number:	Camera/Model:	Inspector:
August 24th, 2021	3BM-WHA2126	Samsung S9	RMO Shouldice
Photo #:		Location:	
5		N/A	
			
Description:			
Water fill station			