

NWB Annual Report

Year being reported:

2009 ▼

2019

License No: 7BL-AWL1722

Issued Date: July 2, 2017

Expiry Date: August 2, 2022

Project Name:

Arctic Watch Lodge

Licensee:

Canadian Arctic Holidays Ltd.

Mailing Address:

Box 1252 Yellowknife

NT

X1A 2N9

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼

Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Cunningham River

Water Quantity:

5

Quantity Allowable Domestic (cu.m)

2.4

Actual Quantity Used Domestic (cu.m)

Quantity Allowable Drilling (cu.m)

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☒ Solid Waste Disposal☒ Sewage☐ Drill Waste☒ Greywater☐ Hazardous☐ Other:

Additional Details:

Shipped to Yellowknife for disposal: household garbage 935lb, 250 lb of recycled glass bottles, 20 gallons of waste oil, 1 car battery, 2 propane refill, 550 lb scrap metal, 6 old ATV tires, 50 lb old hose from DFO. Grey water filtered, then leached back into the ground. Sewage put is a sump.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below



Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below



Additional Details:

Black water sewage sump: 74° 04.213'north, 93° 48.975'
 Incinerator (wood, paper) 74° 04.392north, 93° 48.644'
 Grey water sump/leaching bed 100 m from Black water sump

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Inspection and Compliance Report received by the Licensee (Date): ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

INAC did inspect Arctic Watch in July.

Any additional comments or information for the Board to consider

A mechanical water meter was purchased and installed in June 2019.

Date Submitted:

March 16, 2020

Submitted/Prepared by:

Richard Weber

Contact Information:

Tel: 819 459 1794

Fax:

email: richard@arcticwatch.ca