

NWB Annual Report

Year being reported:

2022

License No: 7BL-AWL1722

Issued Date: July 2, 2017

Expiry Date: August 2, 2022

Project Name:

Arctic Watch Lodge

Licensee:

Weber Arctic Expeditions Ltd.

Mailing Address:

8755 Forsberg rd,
Vernon, BC
V1B3M6

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Weber Arctic Expeditions Ltd.

General Background Information on the Project (*optional):

Annual report for 2022 Arctic Watch Lodge

Licence Requirements: the licensee must provide the following information in accordance with

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Cunningham River

Water Quantity:

5

3.07 cubic Meters / day

Quantity Allowable Domestic (cu.m)

Actual Quantity Used Domestic (cu.m)

Quantity Allowable Drilling (cu.m)

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

Additional Details:

Season total of lodge garbage shipped back to Yellowknife. 1000 lb house-hold garbage, Scrap metal 500lb, 8 x old ATV tires, 5 gal used oil, 130 lb boxed recycled glass, 2 broken mountain bike, 1 John deere UTV, 3 x old camping yurts.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

Additional Details:

Revisions to the spill contingency plan are going to be made for 2023 season.

Revisions to the Abandonment and Restoration Plan

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Additional Details:

Water source 74° 04.167' north, 93° 48.798' west

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Additional Details:

Black water sewage sump: 74° 04.213'north, 93° 48.975' Incinerator (wood, paper) 74° 04.392north, 93° 48.644' Grey water sump/leaching bed 100 m from Black water sump
--

Results of any additional sampling and/or analysis that was requested by an Inspector

Additional Details: (date of request, analysis of results, data attached, etc)

--

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

Additional Details: (Attached or provided below)

--

Any responses or follow-up actions on inspection/compliance reports

Additional Details: (Dates of Report, Follow-up by the Licensee)

--

Any additional comments or information for the Board to consider

The mechanical water meter was working for the season 2022.

Date Submitted:	October 26, 2022						
Submitted/Prepared by:	Nansen Weber						
Contact Information:	<table border="1"> <tr> <td>Tel:</td> <td>2503084656</td> </tr> <tr> <td>Fax:</td> <td> </td> </tr> <tr> <td>email:</td> <td>Nansen@weberarctic.com</td> </tr> </table>	Tel:	2503084656	Fax:		email:	Nansen@weberarctic.com
Tel:	2503084656						
Fax:							
email:	Nansen@weberarctic.com						



