



7BL-EKK1015 Inspection Photos

13 July, 2012



Figure 1. Overview of camp.



Figure 2. Tall propane tank, not fixed to building.



Figure 3. Small propane tank, not fixed to building.



Figure 4. Fuel drum, not in containment.



Figure 5. Propane tanks, littering the ground.