



Field Operations  
Nunavut Regional Office  
PO Box 100  
Iqaluit, NU X0A 0H0

Wednesday, August 15, 2012

(SENT BY E-MAIL)  
CIDM # 554972  
Our File: 7BL-ELU0409

Mr. Luke Coady  
BOX 93  
CAMBRIDGE BAY, NU X0B 0C0  
867-445-8774  
E-mail: luke.coady@hotmail.ca

RE: NWB Licence No. 7BL-ELU0409

Dear Mr. Coady,

I recently was present at your site on July 13, 2012. Please find attached the report of my inspection. There are matters outlined in the report that will require your immediate attention.

Please feel free to contact me to discuss the matters and timelines outlined in this report.

Thank you,

Eva Paul  
Water Resources Officer

Phone: 867-975-4548  
Fax: 867-979-6445  
Mobile: 867-222-6490  
E-mail: [Eva.Paul@aandc-aadnc.gc.ca](mailto:Eva.Paul@aandc-aadnc.gc.ca)

Cc: Andrew Keim, A/Manager, Field Operations, Nunavut Regional Office  
Phyllis Beaulieu, Manager of Licensing, Nunavut Water Board



## WATER USE INSPECTION REPORT

Date: July 13 2012	Licensee Rep. (Name/Title): N/A		
Licensee: Elu Inlet Lodge Ltd.	Licence No.: 7BI-ELU0409		

### **WATER SUPPLY**

Source(s): Pond east of camp	Quantity used: n/a
Owner:/Operator: Luke Coady	

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Intake Facilities: NI	Storage Structure: A	Treatment Systems: NI	Chemical Storage: U
Flow Meas. Device: NI	Conveyance Lines: U	Pumping Stations: NI	Screen : NI

**Comments:** There are hoses laid out, but it is not evident where the water intake went. There are breaks in the lines. Water is piped to each cabin. Chemicals were sitting out in hot tub shelter without secondary containment.

### **WASTE DISPOSAL**

**Sewage:** Sewage Treatment System (Prim./Sec/Ter.): Not evident

Natural Water Body: -	Continuous Discharge (land or water): -	
Seasonal Discharge: -	Wetlands Treatment: -	Trench: -

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Discharge Quality: NA	Decant Structure: U	Erosion: A
Discharge Meas. Device: U	Dyke Inspection: NA	Seepages: NA
Dams, Dykes: NA	Freeboard: NA	Spills: NA
Construction: NA	O&M Plan: NA	A&R Plan: NA
Discharge: U	Effluent Discharge Rate: NA	

**Comments:** Breaks in the line that I assume lead to the sump but which may be the sewage discharge. There are discharges hanging under every cabin that I am assuming are for greywater? This is not acceptable; greywater should be piped out to the sump as well.

### **Solid Waste:**

**Owner/Operator:** Licensee

Landfill: NA	Burn & Landfill: NA	Other: Backhaul
--------------	---------------------	-----------------

**Comments:** There are numerous barrels that require backhaul. They litter the site and the sandbar in front of the site. Some black barrels are half-filled with water, but smell of fuel. Fuel-contaminated water should be backhauled as hazardous waste.

### **FUEL STORAGE:**

**Waste Oil Storage:** None

**Owner/Operator:** Licensee

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Berms & Liners: U	Water within Berms: NA	Evidence of Leaks: A
Drainage Pipes: U	Pump Station & Catchments Berm: U	



<b>Berms &amp; Liners: U</b>	<b>Water within Berms: NA</b>	<b>Evidence of Leaks: A</b>
<b>Pipeline Condition: U</b>	<b>Condition of Tanks: U</b>	

**Comments:** All fuel tanks should be in secondary containment. Berms should be placed under every barrel-stand and fuel tank. Propane tanks have fallen over, putting the connecting line at risk. Old paint cans are evident under a deck. These are also hazardous and should be in a protected environment.

**Non-Compliance of Act or Licence:**

Barrels are to be collected and contained until backhaul is possible. Secondary containment berms are to be placed under every tank that holds fuel, also ensuring that valves and hoses are within containment. Propane tanks are to be secured. Chemicals are to be stored in a protected environment. These are to be completed, and confirmation submitted to the inspector in the form of a short report with photographs by September 30, 2012.

This licence is expired and requires renewal. No annual reports are on-file with the Nunavut Water Board. Annual reports are to be submitted whether or not the site is active.

An application for renewal is to be submitted by November 30, 2012. Annual reports up to current are to be submitted by March 31, 2013.

*Failure to comply with this report may result in enforcement actions being undertaken.*

Eva Paul  
**Inspector's Name**

  
**Inspector's Signature**