

July 13 2012 Inspection of 7BL-ELU0409

Photos



Figure 1. 7BL-ELU0409 from the air.



Figure 2. Water discharge directly under each cabin.

RISKS / Hazardous Waste



Figure 3. Barrels scattered around site.



Figure 4. Pool chemicals in hot tub area.



Figure 5. All fuel barrels should be over a berm.



Figure 6. Containment under valve and hose required.



Figure 7. Propane tank has come loose.



Figure 8. Barrels with no containment.



Figure 9. Barrels on sandbar facing the cabins.



Figure 10. Water coming out of barrel smells of hydrocarbons.

