

**NWB Annual Report**

Year being reported: Select ▼ 1999

License No: 7bl-elu0409 Issued Date:   
Expiry Date:

Project Name: Elu Inlet Lodge

Licensee: Peter Kapolak/Luke Coady

Mailing Address: Box 93  
Cambridge Bay, NU  
X0B 0C0

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

**General Background Information on the Project (\*optional):**

Small Ecotourism lodge

**Licence Requirements: the licensee must provide the following information in accordance with**

Select ▼ Select ▼

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

|                  |                             |                                      |  |
|------------------|-----------------------------|--------------------------------------|--|
| Water Source(s): | <span>Itibiak Lake</span>   |                                      |  |
| Water Quantity:  | <span>50/day</span>         | Quantity Allowable Domestic (cu.m)   |  |
|                  | <span>60 cu m season</span> | Actual Quantity Used Domestic (cu.m) |  |
|                  |                             | Quantity Allowable Drilling (cu.m)   |  |
|                  |                             | Total Quantity Used Drilling (cu.m)  |  |

**Waste Management and/or Disposal**

- ☒ Solid Waste Disposal
- ☒ Sewage
- ☐ Drill Waste
- ☒ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

### Revisions to the Spill Contingency Plan

N/A - not applicable 

Additional Details:

### Revisions to the Abandonment and Restoration Plan

N/A - not applicable 

Additional Details:

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details attached 

Additional Details:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details attached 

Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

Inspection and Compliance Report received by the Licensee (Date): ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

**Date Submitted:**

16/1/2013

**Submitted/Prepared by:**

Luke Coady

**Contact Information:**

**Tel:** 867 445 8774

**Fax:**

**email:** [luke.coady@gov.nt.ca](mailto:luke.coady@gov.nt.ca)