

NWB Annual Report

Year being reported: Select ▼

2019

License No: 7BL-ENN0914

Issued Date: March 1, 2018

Expiry Date: March 1, 2027

Project Name: Arctic Haven Lodge

Licensee: Canadian Arctic Holidays Ltd

Mailing Address: Box 1252 Yellowknife
NT
X1A 2N9**Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):**

Canadian Arctic Holidays operates Arctic Haven Lodge on Ennnadai Lake

General Background Information on the Project (*optional):**Licence Requirements: the licensee must provide the following information in accordance with**

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Ennadai Lake

Water Quantity:

4	Quantity Allowable Domestic (cu.m)
3.2 per day	Actual Quantity Used Domestic (cu.m)
	Quantity Allowable Drilling (cu.m)
	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- Solid Waste Disposal
- Sewage
- Drill Waste
- Greywater
- Hazardous
- Other:

Additional Details:

Shipped to Yellowknife for disposal: household garbage 420kg and waste metal 25kg, glass 135kg, 2 drums waste oil, 64 empty drums.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: 0 (as reported to the Spill Hot-line)

Date of Spill: [redacted]

Date of Notification to an Inspector: [redacted]

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

[redacted]

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

[redacted]

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

[redacted]

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

[redacted]

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below



Additional Details:

Water pump 60° 46' 02"north, 101° 41'19" west

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below



Additional Details:

Septic Tanks / systems 60° 46' 06"north, 101° 46'23" west
Incinerator 101 60° 46' 00"north, 101° 41'32" west

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Inspection and Compliance Report received by the Licensee (Date):

Additional Details: (Dates of Report, Follow-up by the Licensee)

Gravel pit filled in and remediated as requested by the insector

Any additional comments or information for the Board to consider

The lodge was occupied by a small group of caretakers and workers from June to Aug. Generally between 2 to 3 people using less than 1 cubic meter per day. The lodge operated with clients from mid-August to Oct 2, 2019 . The quantity of 3.2 cubic meters per day was during the period with clients.

Date Submitted:

March 17, 2020

Submitted/Prepared by:

Richard Weber

Contact Information:

Tel: 819 459 1794

Fax:

email: richard@arcticwatch.ca