

NWB Annual Report

Year being reported:

2017

License No: 7BL HKO1015 Issued Date: March 22, 2017
Expiry Date:

Project Name: HAKONGAK OUTFITTING

Licensee: George Hakongak

Mailing Address: P.O. Box 2053
Cambridge Bay, NU
X0B 0C0

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Select ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Laughlin River
Water Quantity:	Quantity Allowable Domestic (cu.m)
	Actual Quantity Used Domestic (cu.m)
	Quantity Allowable Drilling (cu.m)
	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
- ☒ Sewage
- ☐ Drill Waste
- ☒ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

All grey water disposed of into the hole dug for the outhouse. Burned cans removed from the burn barrel, packaged up and brought to Cambridge Bay for disposal at the municipal dump.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

Select

Additional Details:

Revisions to the Abandonment and Restoration Plan

Select

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Legacy garbage from commercial fishing activities brought to Cambridge Bay and disposed of at the municipal dump.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below

Additional Details:

N 68° 56' 39.7"
W 108° 32' 12.5"

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

Select ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

Select ▼

Additional Details: (Attached or provided below)

20 gallons of water use a day times 14 days equals 280 gallons

Any responses or follow-up actions on inspection/compliance reports

Select ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

One 12 X 16 weatherhaven frame and covers removed and brought back to Cambridge Bay for disposal at the municipal garbage dump.

Date Submitted:

October 13, 2017

Submitted/Prepared by:

George Hakongak

Contact Information:

Tel: (867) 983-2799

Fax: (867) 983-3190

email: naikak@hakongak.com