Appendix C

Monitoring Program Stations No. ALT-4-5-6-7

Year: 2015

Description: Runoff and Leachate.

Results:

June (Runoff Season)

The Department of National Defence was successful in collecting and analyzing samples at Monitoring Program Station ALT-4during the period of runoff in June 2015. Unfortunately, there were no water to sample at ALT-5-6-7 for analytical results. Analytical Results for ALT-4 are attached in Appendix E.



Photograph of site conditions of ALT-4 in June 2015 to show melt conditions.



Photograph of site conditions of ALT-6 in June 2015 to dry conditions.



Photograph of site conditions of ALT-5 in June 2015 to dry conditions.



Photograph of site conditions of ALT-7 in June 2015 to show dry conditions.

July


Only one Monitoring Program Station (ALT-4) could be sampled in July (picture attached). ALT-5-6-7 showed dry conditions that prevented any water samples to be collected for analysis. Analytical Results for ALT-4 is attached in Appendix F.



Photograph of site conditions of ALT-4 in July 2015 showing surface flow; water samples were obtained.



Photograph of site conditions of ALT-6 in July 2015 to show dry conditions.




Photograph of site conditions of ALT-5 in July 2015 to show dry conditions.



Photograph of site conditions of ALT-7 in July 2015 to show dry conditions.

August

Site visits in August showed dry conditions that prevented any water samples to be collected for analysis at Monitoring Program Stations ALT-4-5-6-7. There are no Analytical Results for August.



September

CFS Alert had returned to winter conditions by late-August, therefore any water sampling for September 2015 could no longer be conducted.