

Appendix C

Monitoring Program Stations No. ALT-4-5-6-7

Year: 2017

Description: Runoff and Leachate.

Results:

June (Runoff Season)

The Department of National Defence was successful in collecting and analyzing samples at Monitoring Program Station ALT-4, during the period of runoff in June 2017. Unfortunately, there were no water to sample at ALT-5, 6, and 7 for analytical results. Analytical Results for ALT-4, are attached in Appendix E.




Photograph of site conditions of ALT-4 in June 2017 to show melt conditions.



Photograph of site conditions of ALT-6 in June 2017 to show dry conditions.



Photograph of site conditions of ALT-5 in June 2017 to show dry conditions.



Photograph of site conditions of ALT-7 in June 2017 to show dry conditions.

July

Only one Monitoring Program Station (ALT-4) could be sampled in July (picture attached). ALT-5-6-7 showed dry conditions that prevented any water samples to be collected for analysis. Analytical Results for ALT-4 is attached in Appendix F.



Photograph of site conditions of ALT-4 in July 2017 showing surface flow; water samples were obtained.



Photograph of site conditions of ALT-6 in July 2017 to show dry conditions.



Photograph of site conditions of ALT-5 in July 2017 to show dry conditions.



Photograph of site conditions of ALT-7 in July 2017 to show dry conditions.

August

Site visits in August was not completed due to unavailable flights to Alert.

Photograph of site conditions of ALT-4 in August 2017 not available.	Photograph of site conditions of ALT-6 in August 2017 not available.
Photograph of site conditions of ALT-5 in August 2017 not available.	Photograph of site conditions of ALT-7 in August 2017 not available.

September

In lieu of August, the DND Team arrived in early-September. CFS Alert had returned to winter conditions by September, therefore any water sampling for September 2017 could no longer be conducted. CFS Alert was snow covered with below zero temperatures.

Photograph of site conditions of ALT-4 in September 2017 not available.	Photograph of site conditions of ALT-6 in September 2017 not available.
Photograph of site conditions of ALT-5 in September 2017 not available.	Photograph of site conditions of ALT-7 in September 2017 not available.