

HOSETRACKER

ONTARIO HOSE SPECIALTIES LTD.

Mississauga	Sarnia	Stoney Creek	Kingston	Quebec	Maritimes
6295 Kestrel Road Mississauga, Ontario L5T 1Z4	480 Polymoor Drive Corunna, Ontario N0N 1G0	263 Barton Street Stoney Creek, Ontario L8E 2K4	639 justus Drive Kingston, Ontario K7M 4H5	1900 Hymus Blvd Dorval, Quebec H9P 1J7	10 Akerley Blvd U#25 Dartmouth, Nova Scotia B3B 1J4
Tel: 905-670-0113 Fax: 905-670-4958	Tel: 519-336-8541 Fax: 519-336-8543	Tel: 905-662-0276 Fax: 905-662-0542	Tel: 613-549-7316 Fax: 613-549-6214	Tel: 514-685-1266 Fax: 514-685-1606	Tel: 902-465-5220 Fax: 902-465-5296

www.ontariohose.com

TEST CERTIFICATE

Customer:	Environment Canada	Fittings:	(SS)MxF (Stainless Steel Male x Female Camlock)
Hose Type:	FLOATER HOSE	Size:	4"
Hose Number:	CAN00003	Length:	400ft
Part Number:	GMFH4X400	HAWP (PSI):	200
Order:		Temperature Range:	
PO:		Rating:	4/5 
Unit Number:		This Hose is in excellent condition and is ok to be in service	
Location:	COAST GUARD	CRN:	N/A
Colour:	-		

Last Test Date

Hydro-Pressure:	5/24/2017
Static:	5/24/2017
Visual:	5/24/2017

Scheduled Retest Date(s)

Hydro-Pressure:	5/24/2018
Static:	5/24/2018
Visual:	5/24/2018

Test PSI:


300

Length of Pressure Test:

Fittings

Reasons for Repair

Clamp/Ferrule	Tube	Cover
---------------	------	-------



Repairs conducted by:

Printed: Wednesday, May 24, 2017
To view as PDF click [here](#)

This report was created by HoseTracker.
Please refer to all instruction manuals, technical drawings and documents before using the above equipment.
All products have been tested and inspected in accordance with the appropriate ANSI stanad.

HOSETRACKER

ONTARIO HOSE SPECIALTIES LTD.

Mississauga	Sarnia	Stoney Creek	Kingston	Quebec	Maritimes
6295 Kestrel Road Mississauga, Ontario L5T 1Z4	480 Polymoor Drive Corunna, Ontario N0N 1G0	263 Barton Street Stoney Creek, Ontario L8E 2K4	639 justus Drive Kingston, Ontario K7M 4H5	1900 Hymus Blvd Dorval, Quebec H9P 1J7	10 Akerley Blvd U#25 Dartmouth, Nova Scotia B3B 1J4
Tel: 905-670-0113 Fax: 905-670-4958	Tel: 519-336-8541 Fax: 519-336-8543	Tel: 905-662-0276 Fax: 905-662-0542	Tel: 613-549-7316 Fax: 613-549-6214	Tel: 514-685-1266 Fax: 514-685-1606	Tel: 902-465-5220 Fax: 902-465-5296

www.ontariohose.com

TEST CERTIFICATE

Customer:	Environment Canada	Fittings:	(SS)MxF (Stainless Steel Male x Female Camlock)
Hose Type:	FLOATER HOSE	Size:	4"
Hose Number:	CAN00002	Length:	400'
Part Number:	GMFH4X400	HAWP (PSI):	200
Order:		Temperature Range:	
PO:		Rating:	4/5 
Unit Number:		This Hose is in excellent condition and is ok to be in service	
Location:	COAST GUARD	CRN:	N/A
Colour:	-		

Last Test Date

Hydro-Pressure:	5/24/2017
Static:	5/24/2017
Visual:	5/24/2017

Scheduled Retest Date(s)

Hydro-Pressure:	5/24/2018
Static:	5/24/2018
Visual:	5/24/2018

Test PSI:

300

Length of Pressure Test:

Fittings	Clamp/Ferrule	Tube	Cover
----------	---------------	------	-------



Repairs conducted by:
Printed: Wednesday, May 24, 2017
To view as PDF click [here](#)

This report was created by HoseTracker.
Please refer to all instruction manuals, technical drawings and documents before using the above equipment.
All products have been tested and inspected in accordance with the appropriate ANSI stanad.

ONTARIO HOSE SPECIALTIES LTD.
HOSETRACKER

Mississauga	Sarnia	Stoney Creek	Kingston	Quebec	Maritimes
6295 Kestrel Road Mississauga, Ontario L5T 1Z4	480 Polymoor Drive Corunna, Ontario N0N 1G0	263 Barton Street Stoney Creek, Ontario L8E 2K4	639 justus Drive Kingston, Ontario K7M 4H5	1900 Hymus Blvd Dorval, Quebec H9P 1J7	10 Akerley Blvd U#25 Dartmouth, Nova Scotia B3B 1J4
Tel: 905-670-0113 Fax: 905-670-4958	Tel: 519-336-8541 Fax: 519-336-8543	Tel: 905-662-0276 Fax: 905-662-0542	Tel: 613-549-7316 Fax: 613-549-6214	Tel: 514-685-1266 Fax: 514-685-1606	Tel: 902-465-5220 Fax: 902-465-5296

www.ontariohose.com

TEST CERTIFICATE

Customer:	Environment Canada	Fittings:	(SS)MxF (Stainless Steel Male x Female Camlock)
Hose Type:	FLOATER HOSE	Size:	4"
Hose Number:	CAN00001	Length:	400'
Part Number:	GMFH4X400	HAWP (PSI):	200
Order:		Temperature Range:	
PO:		Rating:	4/5 
Unit Number:		This Hose is in excellent condition and is ok to be in service	
Location:	COAST GUARD	CRN:	N/A
Colour:	-		

Last Test Date

Hydro-Pressure:	5/24/2017
Static:	5/24/2017
Visual:	5/24/2017

Scheduled Retest Date(s)

Hydro-Pressure:	5/24/2018
Static:	5/24/2018
Visual:	5/24/2018

Test PSI:

300

Length of Pressure Test:

Fittings

Reasons for Repair

Clamp/Ferrule

Tube

Cover



Repairs conducted by:

Printed: Wednesday, May 24, 2017

To view as PDF click [here](#)

This report was created by HoseTracker.

Please refer to all instruction manuals, technical drawings and documents before using the above equipment.
All products have been tested and inspected in accordance with the appropriate ANSI stanad.