



Inspection Report

License #: 3BC-FOH0919

Inspector: A.Keim

CIDMS # 384520

Client	National Defence Canada Nasittuq Corp.		
Mailing Address	Maj. A. Cameron – R&C 3-4 North Warning System Office c/o National Defence Headquarters 101 Colonel By Drive Ottawa, ON. K1A 0K2 Mr. Scott Charland Nasittuq Corp. Suite 100, 170 Laurier Ave W Ottawa, ON K1P 5V5		
Inspection site location	Fox – Main Hall Beach LRR		
Contact name	A. Cameron	Title	O.I.C
Last inspection date	Unknown	July 16,2007	August 10, 2008
Inspection start date	July 20, 2009		
Region	Baffin		



INAC, Nunavut District
Box 100
Building 918
Iqaluit, NU, X0A 0H0

Submitted Via E-Mail
Our File: 3BC-FOH0919
Your File: _____
CIDM # 384520

January 13, 2010

Maj. A. Cameron – R&C 3-4
North Warning System Office
c/o National Defence Headquarters
101 Colonel By Drive
Ottawa, ON. K1A 0K2

Mr. Scott Charland
Nasittuq Corp.
Suite 100, 170 Laurier Avenue West
Ottawa, ON K1P 5V5
E-mail: scott.charland@nasittuq.com

RE: Water Licence Inspection July 18, 2009

The following inspection report is generated on the information collected during a compliance inspection carried out on the Fox -Main, Hall Beach Long Range Radar site and facilities. The inspection was conducted to determine compliance with the terms and conditions of the Water License (3BC-FOH0409) issued to National Defence Canada (DND) by the Nunavut Water Board (NWB).

The report references the applicable parts of the Water License (3BC-FOH0409) and the findings observed under each of those parts. During the writing of this report a compliance review was undertaken of the documents, plans and manuals filed by the Licensee and located on the Nunavut Water Board's FTP site.

The Inspector thanks Mr. Rick Chaulk, Ms. Barb Thomson and Mr. Ivan Pilgram all of Nasittuq Corporation for their assistance, time and advice during the inspection. It is noted that a representative of DND was not present during the inspection as was requested by the Inspector.

* It is noted that the current Water License (3BC-FOH0919) was issued on September 10th, 2009 following the Inspection. The new License addresses a number of the inconsistencies identified by the Licensee and the Inspector.

Issues noted in previous Inspections;

- Open burning of garbage (hazardous wastes)

During the period of the 2009 inspection the following issues were identified by the Inspector;

- None.

Non-Compliance: Issues identified during the July 20th, 2009 inspection and/or review of relevant material

Issues where there is a known or anticipated threat to human health.

- None noted

Issues where there is a known or anticipated environmental impairment;

- None

Issues where there is a known or suspected violation of a requirement of the Water License;

- None

The licensee continues to work on ensuring compliance.



Indian and Northern
Affairs Canada

Affaires indiennes
et du Nord Canada

A. Keim

Inspector's Name

Inspector's Signature

Cc:

Peter Kusugak- Manager Field Operations Section- Indian and Northern Affairs Canada

Phyllis Beaulieu – Manager licensing – Nunavut Water Board





















FOX MAIN - HALL BEACH
2009

Date of Recording	Reading
31 JANUARY 2009	09211550 (02-FEB-09)
28 FEBRUARY 2009	09233195
31 MARCH 2009	09264895 (31-MAR-09)
30 APRIL 2009	92918951 (30-APR-09)
27 MAY 2009	93403000 (27-MAY-09)
30 JUNE 2009	09401010 (30-JUN-09)
31 JULY 2009	
31 AUGUST 2009	
30 SEPTEMBER 2009	
31 OCTOBER 2009	
30 NOVEMBER 2009	
31 December 2009	

