



Photos of July 19 2014 Inspection of 3BC-KAR1319



Figure 1. Compost pits at Karrak Lake shown, rock outlines denotes past pits. One or two added each year.



Figure 2. Burn barrel at Karrak Lake used for 'burnable' waste.



Figure 3. Old waste metal at Perry River cabin.



Figure 4. Litter at Perry River cabin.



Figure 5. Old (full) fuel barrels at Perry River cabin.



Figure 6. Burn site at Perry River cabin.



Figure 7. Fuel cache (A) located on a narrow peninsula. Barrels are now empty, however, the choice of site is contrary to the project's authorizations.



Figure 8. Fuel cache at airstrip across from Perry River cabin.



Figure 9. Fuel cache south of Perry River cabin.



Figure 10. Karrak Lake camp and fuel cache.




Figure 11. Cover page of expired Land Use Permit.