

## NWB Annual Report

Year being reported:

Select



License No:  Issued Date:   
 Expiry Date:

Project Name:

Licensee:

Mailing Address:

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (\*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B



Item 1



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	<input type="text" value="freshwater lakes"/>	
Water Quantity:	<input type="text" value="0"/>	Quantity Allowable Domestic (cu.m)
	<input type="text" value="0"/>	Actual Quantity Used Domestic (cu.m)
	<input type="text" value="NA"/>	Quantity Allowable Drilling (cu.m)
	<input type="text" value="NA"/>	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal  
☐ Sewage  
☐ Drill Waste  
☐ Greywater  
☐ Hazardous  
☐ Other:

Additional Details:

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

To our knowledge, no spills occurred in 2021. We did not visit these field sites.

### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

Spill Contingency Plan revised and submitted in March 2017; no revisions since that date.

### Revisions to the Abandonment and Restoration Plan

No Abandonment and Restoration (AR) Plan submitted or approved

Additional Details:

Abandonment and Restoration Plan revised and submitted in January 2015; no revisions since that date.

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

2021: field sites not visited.

### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details attached

Additional Details:

See 'GPS Coordinates' sheet. However, none of these locations were visited in 2021 due to COVID-19.

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details attached

Additional Details:

See 'GPS Coordinates' sheet. However, none of these locations were visited in 2021 due to COVID-19.

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

**Date Submitted:**

11/14/2021

**Submitted/Prepared by:**

Dana Kellett

**Contact Information:**

**Tel:** 306-514-0460

**Fax:**

**email:** [dana.kellett@ec.gc.ca](mailto:dana.kellett@ec.gc.ca)