



## APPENDIX E1 CULVERTS ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



*Photograph E1-9: Culvert #278 km 61+870*

**Date:** September 10, 2017

**Photo Number:** 364

**Description:** View of culvert inlet, below ground surface, in good condition.



*Photograph E1-10: Culvert #278 km 61+870*

**Date:** September 10, 2017

**Photo Number:** 365

**Description:** View of culvert outlet, obstructed by blocks.



## APPENDIX E1 CULVERTS ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



*Photograph E1-11: Culvert #284 km 63+070*

**Date:** September 10, 2017

**Photo Number:** 361

**Description:** View of culvert outlet, the 2 northern culverts are damaged.

[https://golderassociates.sharepoint.com/sites/16104g/preparation\\_of\\_deliverables/rev0/annexes\\_inspection\\_2017/appendix\\_e - amaruq\\_road/e1 - culverts\\_photo\\_log\\_2017\\_reduit.docx](https://golderassociates.sharepoint.com/sites/16104g/preparation_of_deliverables/rev0/annexes_inspection_2017/appendix_e - amaruq_road/e1 - culverts_photo_log_2017_reduit.docx)



---

**2017 ANNUAL GEOTECHNICAL INSPECTION  
MEADOWBANK GOLD MINE, NUNAVUT**

---

## **APPENDIX E2**

### **Bridges Along Amaruq Road Photographic Log**



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-1 Bridges 1 – km 3+400

Date: September 11, 2017

Photo Number: 509

Description: Looking at the north abutment from downstream.



Photograph E2-2 Bridges 1 – km 3+400

Date: September 11, 2017

Photo Number: 510

Description: Looking at the north abutment from upstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-3 Bridges 1 – km 3+400

Date: September 11, 2017

Photo Number: 507

Description: Looking at the south abutment from downstream.



Photograph E2-4 Bridges 1 – km 3+400

Date: September 11, 2017

Photo Number: 508

Description: Looking at the south abutment from upstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-5 Bridges 2 – km 10+700

Date: September 11, 2017

Photo Number: 495

Description: Looking at the north abutment from upstream.



Photograph E2-6 Bridges 2 – km 10+700

Date: September 11, 2017

Photo Number: 496

Description: Looking at the north abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-7 Bridges 2 – km 10+700

**Date:** September 11, 2017

**Photo Number:** 493

**Description:** Looking at the south abutment from upstream.



Photograph E2-8 Bridges 2 – km 10+700

**Date:** September 11, 2017

**Photo Number:** 494

**Description:** Looking at the south abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-9 Bridges 3 – km 16+000

Date: September 11, 2017

Photo Number: 485

Description: Looking at the north abutment from upstream.



Photograph E2-10 Bridges 3 – km 16+000

Date: September 11, 2017

Photo Number: 486

Description: Looking at the north abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-11 Bridges 3 – km 16+000

**Date:** September 11, 2017

**Photo Number:** 483

**Description:** Looking at the south abutment from upstream.



Photograph E2-12 Bridges 3 – km 16+000

**Date:** September 11, 2017

**Photo Number:** 484

**Description:** Looking at the south abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-13 Bridges 4 – km 20+000

Date: September 11, 2017

Photo Number: 479

Description: Looking at the north abutment from upstream.



Photograph E2-14 Bridges 4 – km 20+000

Date: September 11, 2017

Photo Number: 478

Description: Looking at the north abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-15 Bridges 4 – km 20+000

Date: September 11, 2017

Photo Number: 477

Description: Looking at the south abutment from upstream.



Photograph E2-16 Bridges 4 – km 20+000

Date: September 11, 2017

Photo Number: 476

Description: Looking at the south abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-17 Bridges 5 – km 23+900

**Date:** September 11, 2017

**Photo Number:** 472

**Description:** Looking at the north abutment from upstream.



Photograph E2-18 Bridges 5 – km 23+900

**Date:** September 11, 2017

**Photo Number:** 471

**Description:** Looking at the north abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-19 Bridges 5 – km 23+900

**Date:** September 11, 2017

**Photo Number:** 470

**Description:** Looking at the south abutment from upstream.



Photograph E2-20 Bridges 5 – km 23+900

**Date:** September 11, 2017

**Photo Number:** 469

**Description:** Looking at the south abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-21 Bridges 6 – km 26+100

Date: September 11, 2017

Photo Number: 464

Description: Looking at the north abutment from upstream.



Photograph E2-22 Bridges 6 – km 26+100

Date: September 11, 2017

Photo Number: 463

Description: Looking at the north abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-23 Bridges 6 – km 26+100

Date: September 11, 2017

Photo Number: 462

Description: Looking at the south abutment from upstream.



Photograph E2-24 Bridges 6 – km 26+100

Date: September 11, 2017

Photo Number: 461

Description: Looking at the south abutment from downstream.



---

## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG

---



*Photograph E2-25 Bridges 7 – km 32+300*

**Date:** September 10, 2017

**Photo Number:** 442

**Description:** Looking at the north abutment from upstream.



*Photograph E2-26 Bridges 7 – km 32+300*

**Date:** September 10, 2017

**Photo Number:** 441

**Description:** Looking at the north abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-27 Bridges 7 – km 32+300

**Date:** September 10, 2017

**Photo Number:** 440

**Description:** Looking at the south abutment from upstream.



Photograph E2-28 Bridges 7 – km 32+300

**Date:** September 10, 2017

**Photo Number:** 439

**Description:** Looking at the south abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-29 Bridges 8 – km 43+500

Date: September 10, 2017

Photo Number: 417

Description: Looking at the north abutment from upstream.



Photograph E2-30 Bridges 8 – km 43+500

Date: September 10, 2017

Photo Number: 416

Description: Looking at the north abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-31 Bridges 8 – km 43+500

Date: September 10, 2017

Photo Number: 415

Description: Looking at the south abutment from upstream.



Photograph E2-32 Bridges 8 – km 43+500

Date: September 10, 2017

Photo Number: 414

Description: Looking at the south abutment from downstream.