



APPENDIX A3 BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-21 Bay Goose Dike

Date: September 9, 2017

Photo Number: 310

Description: From approximately Sta. 31+280 on the crest, looking southwest at the downstream slope and the water pond at the downstream toe at Sta. 31+350.



Photograph A3-22 Bay Goose Dike

Date: September 9, 2017

Photo Number: 308

Description: From approximately Sta. 31+280, looking south at the crest.



APPENDIX A3 BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-23 Bay Goose Dike

Date: September 9, 2017

Photo Number: 307

Description: From approximately Sta. 31+280, looking northeast at the crest.



Photograph A3-24 Bay Goose Dike

Date: September 9, 2017

Photo Number: 306

Description: From approximately Sta. 31+490, looking northeast at the downstream toe and slope.



APPENDIX A3 BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-25 Bay Goose Dike

Date: September 9, 2017

Photo Number: 305

Description: From approximately Sta. 31+490, looking west toward Channel 3.



Photograph A3-26 Bay Goose Dike

Date: September 9, 2017

Photo Number: 303

Description: From approximately Sta. 31+475, looking west at the crest and the upstream slope.



APPENDIX A3 BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-27 Bay Goose Dike

Date: September 9, 2017

Photo Number: 304

Description: From approximately Sta. 31+475, looking northeast at the crest and the upstream slope.



Photograph A3-28 Bay Goose Dike

Date: September 9, 2017

Photo Number: 302

Description: From approximately Sta. 31+570, looking north toward Channel 3.



APPENDIX A3 BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-29 Bay Goose Dike

Date: September 9, 2017

Photo Number: 300

Description: From approximately Sta. 31+645, looking east at the crest centreline.



Photograph A3-30 Bay Goose Dike

Date: September 9, 2017

Photo Number: 299

Description: From approximately Sta. 31+645, looking northwest at the crest and the upstream slope.



APPENDIX A3 BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-31 Bay Goose Dike

Date: September 9, 2017

Photo Number: 301

Description: From approximately Sta. 31+640, looking southeast at the upstream slope.



Photograph A3-32 Bay Goose Dike

Date: September 9, 2017

Photo Number: 297

Description: From the crest at approximately Sta. 31+740. Looking southeast downstream toward Channel 3.



APPENDIX A3 BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-33 Bay Goose Dike

Date: September 9, 2017

Photo Number: 298

Description: From the crest at approximately Sta. 31+740, looking north downstream at the water pond at Sta. 31+750.



Photograph A3-34 Bay Goose Dike

Date: September 9, 2017

Photo Number: 295

Description: From approximately Sta. 31+870, looking northwest at the crest and upstream slope.



APPENDIX A3 BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-35 Bay Goose Dike

Date: September 9, 2017

Photo Number: 296

Description: From approximately Sta. 31+870, looking southeast at the crest and upstream slope.



Photograph A3-36 Bay Goose Dike

Date: September 9, 2017

Photo Number: 292

Description: From approximately Sta. 31+920, looking south at the crest.



APPENDIX A3

BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-37 Bay Goose Dike

Date: September 9, 2017

Photo Number: 291

Description: From approximately Sta. 31+920, looking northwest at the crest.



Photograph A3-38 Bay Goose Dike

Date: September 9, 2017

Photo Number: 293

Description: From approximately Sta. 31+920 on the crest, looking southeast at the downstream slope.



APPENDIX A3 BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-39 Bay Goose Dike

Date: September 9, 2017

Photo Number: 294

Description: From about Sta. 31+920 on the crest, looking northwest toward Channel 1 monitoring station.



Photograph A3-40 Bay Goose Dike

Date: September 9, 2017

Photo Number: 288

Description: From approximately Sta. 32+030 looking southeast at the crest.



APPENDIX A3 BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-41 Bay Goose Dike

Date: September 9, 2017

Photo Number: 287

Description: From approximately Sta. 32+030 looking southwest at the crest.



Photograph A3-42 Bay Goose Dike

Date: September 9, 2017

Photo Number: 284

Description: From approximately Sta. 32+015 (south abutment) looking northwest at the crest and downstream slope.



APPENDIX A3 BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-43 Bay Goose Dike

Date: September 9, 2017

Photo Number: 286

Description: From approximately Sta. 32+015 (south abutment) looking east at the crest. Presence of high magnitude settlements in the ultramafic cap placed in the winter of 2013.



Photograph A3-44 Bay Goose Dike

Date: September 9, 2017

Photo Number: 285

Description: From approximately Sta. 32+015 (south abutment) looking southeast at the crest and upstream slope.



APPENDIX A3 BAY GOOSE DIKE PHOTOGRAPHIC LOG



Photograph A3-45 Bay Goose Dike

Date: September 9, 2017

Photo Number: 283

Description: From approximately Sta. 32+025 (south abutment) looking east at the crest. Zone of high magnitude settlement in the ultramafic cap. The tension cracks seem no longer active.



Photograph A3-46 Bay Goose Dike

Date: September 9, 2017

Photo Number: 282

Description: From approximately Sta. 32+025 (south abutment) looking west at the crest. Zone of high magnitude settlement in the ultramafic cap. The tension cracks seem no longer active.



2017 ANNUAL GEOTECHNICAL INSPECTION
MEADOWBANK GOLD MINE, NUNAVUT

APPENDIX A4

Vault Dike Photographic Log and Record of Inspection