

NWB Annual Report

Year being reported: Select ▼ 2019

License No: 8BC-BTN1920

Issued Date: July 22, 2019

Expiry Date: July 21, 2019

Project Name:

Road to Nowhere Bridge Repair

Licensee:

City of Iqaluit

Mailing Address:

City of Iqaluit
 Box 460, Iqaluit, NU
 X0A 0HO

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Concentric Geoscience Inc. (Consultant for the licensee)

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B

▼ Item 1

▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Niaqunguk (Apex) River

Water Quantity:

0	Quantity Allowable Domestic (cu.m)
0	Actual Quantity Used Domestic (cu.m)
0	Quantity Allowable Drilling (cu.m)
0	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- Solid Waste Disposal
- Sewage
- Drill Waste
- Greywater
- Hazardous
- Other:

Additional Details:

No waste generated

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:

(as reported to the Spill Hot-line)

Date of Spill: Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

 No spill occurrence.**Revisions to the Spill Contingency Plan** SCP submitted and approved - no revision required or proposed

Additional Details:

 No revisions made to the SCP since issuance of licence.**Revisions to the Abandonment and Restoration Plan** N/A - not applicable

Additional Details:

 No revisions made to the ARP since issuance of licence.**Progressive Reclamation Work Undertaken** Additional Details (i.e., work completed and future works proposed) N/A - not applicable**Results of the Monitoring Program including:****The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;** Not Applicable (N/A)

Additional Details:

 No water used during construction activities.**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;** Not Applicable (N/A)

Additional Details:

 No waste generated during construction activities.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC

Additional Details: (Dates of Report, Follow-up by the Licensee)

No CIRNAC inspections occurred during construction activities.

Any additional comments or information for the Board to consider

Work was completed at each site in August 2019.

Date Submitted:

October 25, 2019

Submitted/Prepared by:

Daniel Elliot

Contact Information:

Tel: 613-824-8900

Fax: 613-824-8901

email: dan@concentricgeo.com