



## WATER LICENCE INSPECTION FORM

Original  
 Follow-Up Report

Licensee		Licensee Representative						
Dan McQuinn, P. Eng. Stantec Consulting Ltd. 40 Highfield Park Drive, Suite 102 Dartmouth, NS B3A 0A3 Email: <a href="mailto:dan.mcquinn@stantec.com">dan.mcquinn@stantec.com</a>		None Present						
Carey Sibbald Stantech Consulting Limited P.O. Box 1680 Yellowknife, NT X1A 2P3 Email: <a href="mailto:carey.sibbald@stantec.com">carey.sibbald@stantec.com</a>								
Licence No. / Expiry		Representative's Title						
8BD-GIN1112 EXP. 30/06/12								
Land / Other Authorizations		Land / Other Authorizations						
Date of Inspection		Inspector						
13/07/2014		A. Keim						
Activities Inspected		<input type="checkbox"/> Camp <input checked="" type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other: Water Discharge <input checked="" type="checkbox"/> Other: Geotechnical						
Conditions:	A - Acceptable	C - Concern	U - Unacceptable	NA - Not Applicable	NI - Not Inspected			
Water Use	Condition	Comment	Site Conditions	Condition	Comment	Haz/Mat Management	Condition	Comment
Intake/Screen	NA		Water Management Structures	NA		Storage	NA	
Flow Measure. Device	NA		Culverts / Bridges	NA		Spills	NA	
Source:	NA		Drainage	NA		Spill Plan	NA	
Water Use:	NA		Erosion / Sediment	NA				
Recirculation ( y / n )	NA		Mitigation Measures	NA		Administrative		
			Reclamation Activities	NA		Records	NI	
			Materials Storage	NA		Reports	C	2
<b>Waste Disposal</b>			Signage	NA		Plans	C	2
Waste Water	NA					Notifications		
Solid Waste	NA		Monitoring			Other		
Hazardous Waste	NA		Sample Collection / Analysis	NA		Comments		1
*The number in the comments field will correspond with specific comments provided below.								
Samples taken by Inspector:		Location(s):						
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No								

<b>SECTION 1</b>	<input checked="" type="checkbox"/> <b>Comments (s.____)</b>	<input type="checkbox"/> <b>Non-Compliance with Act or Licence (s.____)</b>	<input type="checkbox"/> <b>Action Required (s.____)</b>
<p>On July 13<sup>th</sup>, 2014 An Inspector appointed under the Nunavut Water and Nunavut Surface Rights Tribunal Act attended the site listed in the 2010 application, known locally as the Nanisivik Naval Facility, to inspect the Drilling and test Pit program operated on behalf of the Department of National Defence by Stantec Consulting under the authority of Water License 8BD-GIN1112.</p> <p>Upon arrival at the general location the inspector noted that no evidence of disturbance could be seen related to the diamond drilling locations listed in the application found on line in the Nunavut Water Board's Public Registry.</p> <p>No persons, structures or activities related to the license were found in the area. There were no camp sites associated with the project.</p> <p>On July 13<sup>th</sup>, 2014 the Inspector attended the area both on foot and by helicopter around site coordinates listed in the application submitted to the Nunavut Water Board.</p> <p>A review of the Nunavut Water Board web site (FTP site) cannot locate an Annual Report for the above noted file. As such the Inspector cannot confirm the locations as listed in the application as the locations of any and all associated drill activity conducted under the authority of this license</p>			
<b>SECTION 2</b>	<input type="checkbox"/> <b>Comments (s.____)</b>	<input checked="" type="checkbox"/> <b>Non-Compliance with Act or Licence (s.B(1))</b>	<input type="checkbox"/> <b>Action Required (s.____)</b>
<p>The Licensee is in contravention of the following provision of the issued license 8BD-GIN1112:</p> <p>Part B : General Conditions: Item 1.</p>			



Specifically;

The Licensee has failed to file an Annual Report on the Appurtenant Undertaking with the Board no later than March 31st of the year following the calendar year being reported, containing the following information:

- a. A summary report of water use and waste disposal activities;
- b. A list of unauthorized discharges and a summary of follow-up actions taken;
- c. Any revisions to the Spill Contingency Plan and Abandonment and Restoration Plan, as required by Part B, Item 7, submitted in the form of an Addendum;
- d. A description of all progressive and or final reclamation work undertaken, including photographic records of site conditions before, during and after completion of operations;
- e. A summary of all information requested and results of the Monitoring Program; and
- f. Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

**SECTION 3**  **Comments (s. )**  **Non-Compliance with Act or Licence, (s. )**  **Action Required (s. )**

The Licensee has 30 days from receipt of this report to file the required Annual Reports (2011 and 2012).

If an annual report(s) has been filed, the Proponent is reminded that it is the responsibility of the Licensee to ensure that all submissions to the Board are acknowledged by the licensing department and to ensure it is posted on the Nunavut Water Board Public Registry.

Failure to do so may result in further enforcement action pursuant to the Nunavut Waters and Nunavut Surface Rights Tribunal Act.

#### Photo Log

Date	Authorization	Camera	Inspector
July 13, 2014	8BD-GIN1112	Sony Cyber shot	A. Keim



Figure 1 Overview of test area (drilling)



Figure 2 Overview 2



Figure 3 Looking south from location of proposed drilling activities



Figure 4 Looking North from location of fuel dispensing station

Licensee or Representative	Inspector's Name
	A.Keim
Signature	Signature
	-Sent by Email- Original on file
Date	Date
	July 13, 2014

Office Use Only: Follow-up report to be issued by Inspector

Yes  No