

NWB Annual Report

Year being reported:

2013 ▼

License No: 8BW-CLY1216

Issued Date: February 28, 2014

Expiry Date: March 1, 2016

Project Name: Clyde River Road Construction Project

Licensee: Qikiqtaaluk Corporation

Mailing Address:

PO-Box 1228
Iqaluit, Nu
X0A 0H0

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Qikiqtaaluk Environmental Inc.
Relationship: Consultant & owned 51% by Qikiqtaaluk Corporation

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼

Item 1 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	No water was used during the reporting period		
Water Quantity:		Quantity Allowable Domestic (cu.m)	
		Actual Quantity Used Domestic (cu.m)	
		Quantity Allowable Drilling (cu.m)	
		Total Quantity Used Drilling (cu.m)	

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

No waste disposal was done during the reporting period

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: N/A (as reported to the Spill Hot-line)

Date of Spill: Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

No Spill Contingency Plan (SCP) submitted or approved



Additional Details:

Revisions to the Abandonment and Restoration Plan

No Abandonment and Restoration (AR) Plan submitted or approved



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

No work was undertaken

Results of the Monitoring Program including:**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Select



Additional Details:

No monitoring was done

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Select



Additional Details:

No waste was deposited

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Select ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

QC has not been on the site since the end of activities in 2011.

Date Submitted:

April 30, 2015

Submitted/Prepared by:

Greg Johnson

Contact Information:

Tel: 514-940-3332

Fax: 514-940-3435

email: gjohnson@genv.ca