

## NWB Annual Report

Year being reported: 2014 ▼

License No: 8BW-CLY1216

Issued Date: February 28, 2012

Expiry Date: March 1, 2016

Project Name: Clyde River Road Construction Project

Licensee: Qikiqtaaluk Corporation

Mailing Address: PO-Box 1228  
Iqaluit, Nu  
X0A 0H0

**Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):**

Qikiqtaaluk Environmental Inc.

Relationship: Consultant &amp; owned 51% by Qikiqtaaluk Corporation

## General Background Information on the Project (\*optional):

**Licence Requirements: the licensee must provide the following information in accordance with**

Part B ▼ Item 1 ▼

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s):

No water was used during the reporting period

Water Quantity:

	Quantity Allowable Domestic (cu.m)
	Actual Quantity Used Domestic (cu.m)
	Quantity Allowable Drilling (cu.m)
	Total Quantity Used Drilling (cu.m)

## Waste Management and/or Disposal

- Solid Waste Disposal
- Sewage
- Drill Waste
- Greywater
- Hazardous
- Other:

[Redacted]

## Additional Details:

No waste disposal was done during the reporting period

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.: N/A (as reported to the Spill Hot-line)

Date of Spill: Date of Notification to an Inspector: Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)  
**Revisions to the Spill Contingency Plan**Other: (see additional details) 

Additional Details:

 Spill contingency plan currently under revision and will be submitted within 1 week.**Revisions to the Abandonment and Restoration Plan**Other: (see additional details) 

Additional Details:

 Abandonment and Restoration plan currently under revision and will be submitted within 1 week.**Progressive Reclamation Work Undertaken**

Additional Details (i.e., work completed and future works proposed)

 No work was undertaken**Results of the Monitoring Program including:****The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**Select 

Additional Details:

 No monitoring was done**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**Select 

Additional Details:

 No waste was deposited

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

Inspection Report received by the Licensee (Date):

Additional Details: (Dates of Report, Follow-up by the Licensee)

Inspection report was received on feburary 3rd 2015. A response to the report is being prepared and will be submitted within a week

**Any additional comments or information for the Board to consider**

QC has not been on the site since the end of activities in 2011. The update to the abandonment and restoration plan is in progress and will be submitted next week.

**Date Submitted:**

April 30, 2015

**Submitted/Prepared by:**

Greg Johnson

**Contact Information:**

Tel: 514-940-3332

Fax: 514-940-3435

email: [gjohnson@qenv.ca](mailto:gjohnson@qenv.ca)