



## WATER LICENCE INSPECTION FORM

Original  
 Follow-Up Report

<b>Licensee</b>		<b>Licensee Representative</b>	
Hamlet of Gjoa Haven		David Stockley	
<b>Licence No. / Expiry</b>		<b>Representative's Title</b>	
8BW-GJO1617		Senior Administrative Officer	
<b>Land / Other Authorizations</b>		<b>Land / Other Authorizations</b>	
<b>Date of Inspection</b>		<b>Inspector</b>	
July 11, 2017		Baba Pedersen	
<b>Activities Inspected</b>			
<input type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input checked="" type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other: <input checked="" type="checkbox"/> Other: Bridge Construction Project			

<b>Conditions:</b>	<b>A - Acceptable</b>	<b>C - Concern</b>	<b>U - Unacceptable</b>	<b>NA - Not Applicable</b>	<b>NI - Not Inspected</b>			
<b>Water Use</b>	Condition	Comment	<b>Site Conditions</b>	Condition	Comment	<b>Haz/Mat Management</b>	Condition	Comment
Intake/Screen			Water Management Structures	A	2	Storage		
Flow Measure. Device			Culverts / Bridges	A	1	Spills		
Source:			Drainage			Spill Plan		
Water Use:			Erosion / Sediment					
Recirculation ( y /n)			Mitigation Measures			<b>Administrative</b>		
			Reclamation Activities	A	2	Records		
			Materials Storage			Reports		
<b>Waste Disposal</b>			Signage			Plans		
Waste Water						Notifications		
Solid Waste			<b>Monitoring</b>			<b>Other</b>		
Hazardous Waste			Sample Collection / Analysis					

\*The number in the comments field will correspond with specific comments provided below.

Samples taken by Inspector:	Location(s):
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

<b>SECTION 1</b>	<input checked="" type="checkbox"/> <b>Comments (s.____)</b>	<input type="checkbox"/> <b>Non-Compliance with Act or Licence (s.____)</b>	<input type="checkbox"/> <b>Action Required (s.____)</b>
I Inspected the Gjoa Haven Bridge Construction Project (Photos 1 to 4) located at N 68° 38' 13.4" W 095° 59' 41.4" on July 11, 2017. I was accompanied by Adam Halluqtaliq and Dominique Qirqqut from the Hamlet of Gjoa Haven and Shah Alam from GN CG&S.			
<b>SECTION 2</b>	<input checked="" type="checkbox"/> <b>Comments</b>	<input type="checkbox"/> <b>Non-Compliance with Act or Licence</b>	<input type="checkbox"/> <b>Action Required</b>
1. I was told the Bridge had been completed in September 2016 and I found it to actively being used. 2. The Bridge, Access Ramps and surrounding River area are in a Clean and Natural State.			
<b>SECTION 3</b>	<input type="checkbox"/> <b>Comments</b>	<input type="checkbox"/> <b>Non-Compliance with Act or Licence</b>	<input checked="" type="checkbox"/> <b>Action Required</b>
I recommend Closure of Water License 8BW-GJO1617.			

<b>Licensee or Representative</b>	<b>Inspector's Name</b>
	Baba Pedersen
<b>Signature</b>	<b>Signature</b>
	Signed Original on File
<b>Date</b>	<b>Date</b>
	22 Feb 2018

Office Use Only: Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---


CC:      licensing@nwb-oen.ca  
 Manager of Field Operations, INAC  
 Shah Alam, Municipal Engineer, Gov't of Nunavut



PHOTO LOG



Description: View from Town Side of Bridge – Project is Complete – Road and Bridge are Actively in Use



Description: Photo of GPS showing location of Center of Bridge



Photo Log # DSC09987

Location (N 68° 38' 13.4" W 095° 59' 41.4")

Photo 3



Description: Close-up view of top of Bridge looking towards town

Photo Log # DSC09990

Location (N 68° 38' 13.4" W 095° 59' 41.4")

Photo 4



Description: Side View of Bridge showing Foundation