



WATER LICENCE INSPECTION FORM

Original
 Follow-Up Report

Licensee	Licensee Representative				
Government of Nunavut	NA				
Licence No. / Expiry	Representative's Title				
8BW-NAC0606	NA				
Land / Other Authorizations	Land / Other Authorizations				
--					
Date of Inspection	Inspector				
June 8, 2021	Jonathan MESHER				
Activities Inspected					
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input checked="" type="checkbox"/> Construction	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Fuel Storage
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Other:	<input type="checkbox"/> Other:			

Conditions:	A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected
Water Use	Condition	Comment	Site Conditions	Condition	Comment
Intake/Screen	A		Water Management Structures	NA	Storage
Flow Measure. Device	NA		Culverts / Bridges	NA	Spills
Source:	NA		Drainage	NA	Spill Plan
Water Use:	NA		Erosion / Sediment	NA	
Recirculation (y /n)	NA		Mitigation Measures	A	Administrative
			Reclamation Activities	NA	Records
			Materials Storage	NA	Reports
Waste Disposal		Signage		Plans	NI
Waste Water	NA			Notifications	A
Solid Waste	NA		Monitoring		Other
Hazardous Waste	NA		Sample Collection / Analysis	A	Follow-up from previous inspection

*The number in the comments field will correspond with specific comments provided below.

Samples taken by Inspector:	Location(s):
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Background			
<p>This Licence allows for an undertaking classified as Miscellaneous as per Schedule II of the Regulations, to construct (relocate) a ditch to redirect snow melt and surface runoff around the proposed site of construction for three (3) new student residences and a daycare at the Nunavut Arctic College in Iqaluit, located on the northwest corner Saputti Drive and Qulliq Court as shown in the Site Plan and as identified in the report accompanying the Application.</p>			
Inspection			
<p>On June 8th, 2021 Jonathan Mesher, Crown Indigenous Affairs and Northern Relations Canada Inspector, did perform an inspection of the Water Licence 8BW-NAC0606 located in Iqaluit, Nunavut, the below observations were noted.</p>			
<p>Observations:</p> <ol style="list-style-type: none"> 1. The armouring installed appears to be effectively preventing erosion. 2. At the time of the inspection some of the ditch was still frozen. 3. No work was water use or deposit of waste was observed during the inspection and no concerns were noted, The inspector is requesting this licence be closed. 			

**SECTION 2** **Comments** **Non-Compliance with Act or Licence** **Action Required**

Click here to enter text.

Inspector's Name Jonathan MESHER	
Signature 	
Date June 8, 2021	

Water Resource Officer, Nunavut Region
Crown Indigenous Relations and Northern Affairs Canada – CIRNAC
Jonathan.mesher@canada.ca
Office #: 867-222-0118
Fax: 867 979-6445

Date	Camera	Inspector	Authorization
	Sony Cyber-shot	J.Mesher	8BW-NAC0606
Photo Log			
Photo 1			
			
Description: Ditch constructed under this licence.			