



Photo 9 CRS-2 crossing culvert and upstream pond substrate; west aspect.




Photo 10 Stream flow pattern upstream of CRS-3 with existing ATV trail and proposed access road route on the left side of the photo; southeast aspect.

Appendix B: Waterbody Crossing Photographs




Photo 11 **East aspect of impacted stream banks at existing ATV trail stream crossing; site is also CRS-3 crossing of the proposed access road at Km 3.5.**



Photo 12 **Stream reach upstream of CRS-3; north aspect.**



Photo 13 CRS-3 crossing site and stream reach downstream; south aspect.



Photo 14 Natural bank structure upstream of CRS-3; note slight undercut banks and high water level due to spring freshet.



Photo 15

Stream reach downstream of CRS-4 crossing with snowpack; north aspect.



Photo 16

North of CRS-4 crossing stake, note snowpack and boulders; south aspect.