



Photo 17

Large snowpack along stream and stream substrate downstream of CRS-4 crossing; southeast aspect.




Photo 18

CRS-5 crossing located at Km 5.0 of the access road, note snow cover present; southeast aspect.


Appendix B: Waterbody Crossing Photographs



Photo 19 Stream reach upstream of CRS-5 crossing with potential barrier to fish passage, northeast aspect.



Photo 20 Stream reach downstream of CRS-5 crossing, note snow cover present; south aspect.

**Photo 21**

CRS-6 crossing stake located at Km 6.2 of the access road, note lack of defined channel at crossing and existing ATV trail in background; north aspect.

**Photo 22**

Stream reach upstream of CRS-6 with defined channel, note altered channel at a previous ATV crossing; north aspect.

Appendix B: Waterbody Crossing Photographs



Photo 23 Wide spread flow pattern with ATV tracks across flow; existing ATV trail in background; southwest aspect.



Photo 24 Stream reach downstream of CRS-6 crossing site with defined channel; south aspect.