



Photo 25

CRS-7 crossing located at Km 7.2 of the access road, north aspect.



Photo 26

Stream reach at the CRS-7 crossing, note stream substrate and shallow water depth; south aspect.

Appendix B: Waterbody Crossing Photographs



Photo 27 **ATV crossing site upstream of CRS-7, note altered substrate and widened channel; north aspect.**



Photo 28 **Stream reach downstream of CRS-7, drainage lake in background with partial ice cover; south aspect.**